

Date of writing Report 12-6-37. When handed in at Local Office 26-6-37 Port of Leith.

No. in Reg. Book. Survey held at Burntisland Date, First Survey 26-5-37 Last Survey 10-6-1937 (No. of Visits 3.)

on the Machinery of the ~~Wood, Iron or Steel~~ S.S. "CORFIELD."

Tonnage { Gross 1791.44 Net 1004.28 Vessel built at Burntisland By whom Burntisland, J.B. & Co. Ltd. When 1937

Engines made at Sunderland By whom N.E. Marine Eng. Co. Ltd. When (Donkey)

Nominal Horse Power { Boilers, when made (Main) Owners Wm. Gray & Son, Ltd. Owners' Address (if not already recorded in Appendix to Register Book.) Port London Voyage

No. of Main Boilers Managers

No. of Donkey Boilers Steam Pressure in Main Boilers

in Donkey Boilers

Surveyed Afloat or in Dry Dock On Stocks (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. Port

Particulars of Examination and Repairs (if any) Fitting Out.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Did the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

The sea-cocks and valves have been efficiently fitted in place, and the stern frame has been bored out to receive the stern tube.

The bilge suction pipes to the holds are carried through the cross bunker, protected by wood ceiling.

The vessel is being towed to Sunderland to have the Engines, Boilers fitted on board, and the survey will be completed at that port. Surveyors advised.

The dates of survey are as follows:-

Stern frame bored out:- 26-5-37.

Engine & boiler seatings:- 2-6-37.

Completion of fitting sea-cocks:- 10-6-37.

General Observations, Opinion, and Recommendation:- The above information is forwarded for

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, S.&M.S. 2, 11, & L.M.C. 2, 11, or

the consideration of the Committee.

Survey Fee (per Section 29) £ : : Fees applied for

Special Damage or Repair Fee (if any) (per Section 29.) £ : : Received by me,

Travelling expenses (if chargeable) £ : : 19

Committee's Minute See above F.E. rpt WED 4 AUG 1937

Assigned

J. Campbell 1920 Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to

Await
Rpl. H.C.



© 2020
Lloyd's Register
Foundation