

# Report of Survey for Repairs, &c., of Engines and Boilers.

JAN 30 1940

(Received at London Office)

Date of writing Report 15/1/40. When handed in at Local Office 15/1/40. Port of GENOA.  
 Survey held at GENOA. Date, First Survey 8/1/40 Last Survey 10/1/40 19X  
 (No. of Visits Three)  
 on the Machinery of the XXXXXXX Steel Sc. "MARIN SANUDO" Year. Month. 1926 12  
 Gross 5081 Vessel built at Monfalcone By whom Cant. Nav. Triestino When 1926  
 Net 3139 Engines made at Trieste By whom Stab. Tecnico When 1926  
 489 Boilers, when made (Main) - (Donkey) -  
 Owners LLOYD TRIESTINO D. A. di New Owners' Address Venice Voyage ---  
 Managers -  
 If Surveyed Afloat or in Dry Dock Afloat Genoa Harbour  
 (State name of Dock.) & Grazie Dry Dock.  
 Donkey Boilers 100 lb.

st Report No. Port \* LMC. C.S., DBS.  
& DOCKING.

Particulars of Examination and Repairs (if any) 100 A.I.  
5-39  
ss. Gen. N°3-12-38  
TS. CL. 8-38

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
 CHARACTER. 100 A.I.  
 Date of last Survey and of Periodical Surveys. 5-39  
 Machinery and Boiler Survey (including date of N.B. if any). LMC. CS. 5-38  
DBS. 12-36  
DBS. 12-38  
TS. CL. 8-38

damage cases where the Surveyor has not made a special damage report he is required to state whether he

offered his services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

" " Donkey " " " "

this was not done, state for what reasons? ---

and what parts of the Boilers could not be thus thoroughly examined?

so what special means, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

ate latest date of internal examination of Donkey boiler D.B. 8/1/40.

did the Surveyor examine the Safety Valves of the Main Boiler? --- To what pressure were they afterwards adjusted under steam? ---

did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? 90 lbs. (see Below)

did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? --- and of the Donkey Boilers? Yes

did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? --- and of the Donkey Boilers? ---

did the Surveyor examine the drain plugs of the Main Boilers? --- and of the Donkey Boilers? Yes

did the Surveyor examine all the mountings of the Main Boilers? --- and of the Donkey Boilers? ---

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? --- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ---

Has shaft now been changed? --- If so, state reasons --- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ---

Has the shaft now fitted been previously used? --- Has it a continuous liner? --- Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ---

State date of examination of Screw Shaft --- State the distance between lignum vitae or 4 m/m.

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ---

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ---

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. It was stated that the L.M.C. C.S.

would be advanced from time to time in accordance with Circular N°1670.

NOW DONE FOR L.M.C. C.S.- Examined the following parts:-

Main Engine- N°4 cylinder, cover, piston, piston rod, crosshead, top end bearings, connecting rod, valves &

valve gear. Nos. 6, 7 & 8 crankshaft journals and main bearings.

Main Engine/blast air receiver (N°4) internally.

Starboard starting air receiver (N°1) internally.

REPAIRS- Main Engine- N°4 top end bearings remetalled.

N°7 main bearing (top half) remetalled.

N.B. No Interim Certificate issued in this case but a note of the items examined

was made in a book kept aboard by the Chief Engineer. P.T.O.

General Observations, Opinion, and Recommendation:— The machinery of this vessel, so far as now

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, B.M.S. 2, 11, & L.M.C. 2, 11, or

any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, B.M.S. 2, 11, & L.M.C. 2, 11, or

seen, is in good condition and eligible, in my opinion, to remain as classed with fresh record of

D.B.S. I-40 and \* L.M.C. C.S. (with date) on completion of the survey.

Survey Fee (per Section 29) \* LMC. CS. Lit. 100.-

Special Damage or Repair Fee (if any) D.B.S. 185.-

Travelling expenses (if chargeable) Docking 150.-

Committee's Minute 4.38

Assigned ---

Fees applied for 18/1/40

Received by me, ---

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

007909-007918-0327 1/2

D.B.S.- Examined the Donkey Boiler internally and externally together with all mountings and doors. Found generally in good condition. Safety valves of Donkey Boiler adjusted under steam to 90 lbs/sq.inch. (It was stated by the Chief Engineer that a steam pressure of 90 lbs/sq.inch was sufficient).

DOCKING- Vessel placed in dry dock.

Examined the propeller, aft end of stern bush, and fastenings of all underwater connections.

All sea valves opened up and examined. All found or replaced in good condition.

446

5m 11.38. (MADE IN ENGLAND.)