

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

Date of writing Report June 14<sup>th</sup> 41. When handed in at Local Office June 27 41 Received at London Office June 27 41 Port of New York USA

No. in Reg. Book. 86099 Survey held at Broadway New York Date, First Survey May 10<sup>th</sup> 1941 Last Survey May 21<sup>st</sup> 1941 (No. of Visits 5)

on the Machinery of the Wood, Iron or Steel WASHINGTON

Tonnage { Gross 7030 Vessel built at Oakland Bay By whom Moore Ship Co. Year. Month. 1920 6  
Net 4352 Engines made at Los Angeles Bay By whom Leewards Iron Works When 1920

Nominal Horse Power 579 Boilers, when made (Main) 1920 (Donkey) 1920

No. of Main Boilers 318 Owners The Texas Co. Owners' Address As given  
(if not already recorded in Appendix to Register Book.)

No. of Donkey Boilers 210 Managers Do. Port Washington Detoyage

in Main Boilers 210 If Surveyed Afloat or in Dry Dock Port  
(State name of Dock.) Robt. D.D. Brooklyn.

in Donkey Boilers 210 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. ✓ Port ✓

## Particulars of Examination and Repairs (if any)

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

Was this not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? ✓ No

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 8 1/2"

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted? Yes

Did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

Is the Survey not complete, state what arrangements have been made for its completion and what remains to be done

Complete in respect to this

## Particular Survey

Propeller, stem bush & fastenings examined.

The Main engines overhauled, Cylinders skinned up & pistons renewed. Crank shaft remover machine & re-setter. All bearings re-setter & secured in housing & sole plates. Crank rods overhauled, frames re-setter together with 1st & 2nd bottom Cr.T. also eccentric strips. Main steam piping & spacers with 1st & 2nd Pump Parts.  
1st Cyl dia 25 3/4", 1st Cyl Dia 42 3/4", 2nd Cyl Dia 72 3/4".

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.S.M.S. 9, 11, & L.M.C. 9, 11, or L.M.C. 140 lb., F.D., &c.)

Machinery eligible to be retained as classed.

as recorded.

Survey Fee (per Section 20) £ : : Fees applied for 1941  
Special Damage or Repair Fee (if any) £ 50  
(per Section 20.)  
Travelling expenses (if chargeable) £ : : Received by me, 19

Committee's Minute

Signed As above

NEW YORK JUL 2 1941

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register  
Foundation

007958-007966-0194



For A.B. Amend cy-dize \$  
25 <sup>1</sup>/<sub>16</sub>, 42 <sup>1</sup>/<sub>16</sub> + 72 <sup>5</sup>/<sub>16</sub>.

27  
20/8/41

1871

७

三

*[Faint handwritten text, likely bleed-through from the reverse side of the page.]*

*[Faint handwritten cursive script]*

*[Faint handwritten notes in cursive script, likely bleed-through from the reverse side.]*

*[Handwritten notes, mostly illegible due to extreme blur and slant.]*

© 2020

Lloyd's Register  
Foundation