

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report 26th April, 40 When handed in at Local Office 26th April 40 Port of Gothenburg
No. in Survey held at Gothenburg Date, First Survey 10th April Last Survey 18th April 1940
Reg. Book. 29784 on the Machinery of the Wood, Iron or Steel 1/2 MINNA. (No. of Vessels 2)
Tonnage { Gross 1365 Vessel built at Aberdeen By whom J. Lewis & Sons, Ltd. When 1923 4
Net 810 Engines made at Aberdeen By whom J. Lewis & Sons, Ltd When 1923
Nominal Horse Power 179 Boilers, when made (Main) 1923 (Donkey) -
No. of Main Boilers 2 Owners Kasnu Laeva - Omanikud Owners' Address -
No. of Donkey Boilers 1 Manager O. Viedemann (if not already stated in Appendix to Register Book.)
Steam Pressure in Main Boilers 180 lb Port Kasnu Voyage -
No. of Donkey Boilers 1 If Surveyed Afloat or in Dry Dock Afloat Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

ast Report No. - Port -
Particulars of Examination and Repairs (if any) Part BS & Cond. Surv.
Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.
damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined
as a damage report made by anyone else? If so, by whom?
the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes
" " Donkey " " " -
this was not done, state for what reasons?
what parts of the Boilers could not be thus thoroughly examined?
what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
the latest date of internal examination of each boiler Port 18.4.40. Harboard 10.4.40. Present condition of funnel(s) Good
the Surveyor examine the Safety Valves of the Main Boiler? Yes To what pressure were they afterwards adjusted under steam? Not adjusted
the Surveyor examine the Safety Valves of Donkey Boiler? - To what pressure were they afterwards adjusted under steam? -
the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes , and of the Donkey Boilers? -
the Surveyor examine the drain plugs of the Main Boilers? Non , and of the Donkey Boilers? -
the Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers? -
screw shaft now been drawn and examined? - Is it fitted with continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -
shaft now been changed? - If so, state reasons
the shaft now fitted been previously used? - Has it a continuous liner? - Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? -
date of examination of Screw Shaft - State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft
Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes
did the Surveyor examine the generators, motors, switchgear, cables and fuses? No
the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No
e Survey is not complete, state what arrangements have been made for its completion and what remains to be done See below

Now done:
Both boilers examined in- and externally with safety valves and mountings.
Main- and auxiliary machinery examined as far as practicable.
To complete BS:
The safety valves of both boilers to be adjusted under steam. It is stated that this will be done at the first convenient opportunity.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is
State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, & L.M.C. 9,11, or L.M.C. 140 lb., E.D., &c.)
legible in my opinion to remain as now classed in the Register Book and when the survey has been completed to have record of BS 4.40.

Fee (per Section 29) £r 75.00 Fees applied for 16th April 40
Damage or Repair Fee (if any) £ Received by me, 19
Other expenses (if chargeable) £
Committee's Minute As now FRI 14 JUN 1940
Signed As now

J. Agulim © 2020
Engineer Surveyor to Lloyd's Register of Shipping.
Lloyd's Register Foundation