

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office _____)

Date of writing Report.....24.....1.....19.51..... When handed in at Local Office.....19.....

Port of Curacao, N. W. I.

No. in Survey held at Willemstad, Curacao, N.W.I. Date. First Survey 21.1.51 Last Survey 22.1.19.51

g. Book. (No. of Visits.....2.....)

936 on the Machinery of the ~~Wood, Iron or~~ Steel T. S. M. V. " J A C O "

Gross 1344 Vessel built at Middlesbro' By whom Cleveland Dockyard When 1945

Net 719 Engines made at Colchester By whom Davey, Paxman & Co. Ltd When 1944

1184 Boilers, when made (Main) (Donkey)

Owners J. Asmussens Eftf. Owners' Address (if not already recorded in Appendix to Register Book.)

Managers Port Copenhagen Voyage

If Surveyed Afloat or in Dry Dock (State name of Dock.) Wilhelmina

Report No. Port

Particulars of Examination and Repairs (if any) Docking

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years assigned now	Machinery and Boiler Surveys
* for Special Survey. Date of last Survey and of Periodical Surveys.	expired.	(including date of N.B., if any)
A1 12.49		LMC 1.48
ss. Cpn. - 1.48		NE (p&s inbd) made 44 fitted 1.50.
for service in the Gulf of Mexico, Caribbean Sea & coasting through Panama Canal to Balboa		TS 10.49

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

ot, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Latest date of internal examination of each boiler

Present condition of funnel(s)

Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the

Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Done:- Vessel placed in drydock, propellers and outside fastenings examined and found or placed good order.

airs:- The propellers were removed to renew the zinc ring at after end of strut bearing and when screwshafts were examined they were found to be badly corroded at top of taper. As there were spare screwshafts on board these could not be changed.

is recommended that these screwshafts be renewed by 7.51.

General Observations, Opinion, and Recommendation:- The machinery of this vessel as now seen is eligible

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9.11, B&MS 9.11 *LMC 9.11 or *LMC 140 lb., FD, &c.) CS 2.24,

my opinion to be retained as now classed without fresh record of survey subject to Port and

board Screwshafts being renewed by 7.51.

Survey Fee (per Section 29) £ : : Fees applied for

al Damage or Repair Fee (if any) £ : : 19

elling expenses (if chargeable) £ : : Received by me, 19

Committee's Minute WFA 21 MAR 1951

igned As now, subject

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation