

501 on the Machinery of the ~~Work,xxxxx~~ Steel Oil Barge "Y.126"

Gross 548

Net 321

Final 142NHP

Power

Main Boilers

Donkey Boilers

Pressure

Main Boilers

Donkey Boilers

Vessel built at Quincy, Mass.

Engines made at Cleveland

Boilers, when made (Main)

Owners United States War Shipping Administration

Managers

Surveyed Afloat & in Dry Dock Wapping Dry Dock

(State name of Dock.)

By whom Bethlehem S.B. Corp. Ltd.

By whom Winton, Eng. Corp.

(Donkey)

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Wilmington

Voyage

When 1930 5

When 1930 5

Report No. Port

Particulars of Examination and Repairs (if any) Examination

al Surveys, when held, must be reported in detail and serial in the terms of the Rules. State clearly the cause of Repairs, if any, detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly ised at the end of the report. State also the dates and initials of any letters respecting this case.

ge cases where the Surveyor has not made a special damage report he is required to state whether he offered his ices for this purpose, and why they were declined

amage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey

state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

pecial means, in the absence of internal examination, were adopted by the

yor to assure himself of the thorough efficiency of those parts of each Boiler?

est date of internal examination of each boiler

Present condition of funnel

Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

screw shaft now been drawn and examined? No

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

t now been changed?

If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

proved oil retaining appliance fitted at the after end?

State date of examination of Screw Shaft

State the wear down in the

ush 3/32"

Is electric light and power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

Engine parts, when referred to by numbers, should be counted from forward.

urvey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

An examination of vessel was requested for purpose of ascertaining her condition after having made the ocean voyage from the United States of America.

Vessel in dry dock, propeller, outer end of stern bush and outside fastenings of sea connections examined and found in good order. The machinery throughout generally examined externally without any parts being opened for inspection. The diesel generator engines seen under working conditions, starting easily and during the time of running working satisfactorily, and the machinery, so far as seen, appears to be satisfactory. The Chief Engineer, however, reported there are certain minor defects which were not apparent and, at present, are not considered to be of immediate importance. The generators, motors, switchgear, cables and fuses generally examined and found in good order, insulation tests were not taken.

l Observations, Opinion, and Recommendation:— This vessel's machinery, so far as seen, is in  
state clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required  
to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 \*LMC 9,11 or \*LMC 140 lb., FD, &c.)  
CS 3,34,  
good order and eligible in my opinion to remain as classed in the Register Book.

£ : : Fees applied for

19

£ : : Received by me,

19

Expenses (if chargeable) £ : :

FRI, 13 APR 1945

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

008231-008236-0148