

B.C.

No. 56654

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

23 MAR 1950

(Received at London Office)  
 Date of writing Report 20th March 1950 When handed in at Local Office 22 March 1950 Port of CARDIFF

Survey held at CARDIFF Date. First Survey 3rd Jan 1950 Last Survey 9th March 1950  
 Book. 159 on the Machinery of the Wm. Trawler "SASEBO" (No. of Visits 12)

Gross 308 Vessel built at Middlesbrough By whom Smith's Dock Co. When 1928 12

Net 161 Engines made at Middlesbrough By whom Smith's Dock Co. When 1928

Boilers, when made (Main) 1928 (Donkey)

Owners' Address Neale & West Ltd. Port Cardiff Voyage

Managers Neale & West Ltd. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If Surveyed Afloat in Dry Dock Hills Dry Dock & West Dock.

st. Report No. Port

Particulars of Examination and Repairs (if any) Docking MBS & T.S. BS\* Fishing MBS\* 2,46

Annual Survey 2,46 Blr.S. 6,49

SS. Off. 2,46 msp 2,46

TS (CL) 5,48

services for this purpose, and why they were declined

as a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yes

Donkey " " " " " " " " " " " "

not, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

Present condition of funnel(s) Efficient

the latest date of internal examination of each boiler 6th. February 1950

the Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 180lbs.

the Surveyor examine the Safety Valves of the Donkey Boilers? yes To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers?

the Surveyor examine the drain plugs of the Main Boilers? yes and of the Donkey Boilers?

the Surveyor examine all the mountings of the Main Boilers? yes and of the Donkey Boilers?

the screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? 2

shaft now been changed? no If so, state reasons no Has the shaft now fitted been previously used? no Has it a continuous liner? no

an approved oil retaining appliance fitted at the after end? no State date of examination of Screw Shaft 23-2-50 State the wear down in the

stern bush close Is electric light yes fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? yes

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? yes

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete.

Docking MBS. Blr.S. & T.S.

Vessel placed in dry dock, propeller, stern bush and sea connections, outside fastenings examined.

Screw shaft drawn and examined.

Main engine covers, cylinders, valve chests, pistons, valves, rods, spindles, bottom end pins and

crasses, main journals and bearings, thrust shaft, bearings, collars and liners, main engine attached

pumps, general service and auxiliary feed pumps, independent circulating pump, dynamo, steering and

indlass engines, main condenser (tested), valves, strums and pipes of pumping arrangements examined

and tested. Sea inlet and discharge valves, all now examined and found or placed in efficient

condition,

main boiler examined internally and externally together with all mountings, manhole doors and their

fastenings, all found, or placed in efficient condition. Safety valves adjusted to pressure stated

above and found efficient.

generator fittings on main and sub-distribution boards examined, insulation resistance measured P.T.O.

General Observations, Opinion, and Recommendation:— The Machinery of this vessel so far as now seen is in

efficient condition and is eligible in our opinion to remain as classed and to have the records

of M.B.S.\* 3,50 Blr.S. 3,50 TS (CL) 2,50, Annual Survey 3,50

Survey Fee (per Section 29) M.B.S. 8 : 8 : 0 Fees applied for

Blr.S. 3 : 0 : 0 22 Mar 1950

Special Damage or Repair Fee (if any) T.S. 1 : 0 : 0 Received by me, Andrew J. Cant

(per Section 29) Elect. Light 3 : 0 : 0 19

Travelling expenses (if chargeable) Repairs 8 : 8 : 0

Committed's Minute TUES. 18 APR 1950

Assigned MBS \* 3,50

S (CL) 2,50 Blr. S. 3,50

CERTIFICATE WRITTEN

Lloyd's Register



and found, or brought up to the Rule requirements. Installation examined under working conditions and found efficient.

Repairs now Effected:- All sea inlet valves opened up, completely overhauled and closed up. Main Engine attached pumps- Rams machined, neck and gland bushes renewed. Crank shaft lifted for examination of lower half of No.4 main bearing, all bearings cleaned up and shaft rebedded. Stern bush rewooded, tail shaft landed and new propeller fitted. Dynamo engine - New piston rings fitted, bottom end brasses remetalled, top end pin machined, and new Gunmetal bush fitted. Windlass engine - new piston rings fitted all bearings adjusted. General Service Pump - Buckets renewed, new piston rings fitted, valve gear completely overhauled. Auxiliary Feed Pump - Water end liners (2) bored out new buckets fitted, piston rings renewed, valve gear completely overhauled

Main Boiler - All mountings completely overhauled, and placed in efficient condition. All plain tubes removed together with the following screwed stay tubes, Port Wing - 18 Centre 4, Starboard Wing 18 tube plate specially examined when tubes removed 25 screwed stay tube holes built up and holes retapped. Port Wing - 1 back screwed combustion chamber stay renewed. Lower manhole flanges built up and door refitted, 4 studs of lower doors renewed.

Electrical Repairs Foremast cable from junction box at foot of mast to light, part renewed. Wiring in engine and boiler rooms part renewed where damaged. Dynamo governor tested under working conditions and found in order.

On completion of repairs the main and auxiliary machinery were examined under working conditions and found efficient

*A. J. Cant*

The Machinery of this vessel so far as now seen is in efficient condition and is eligible in our opinion to remain as classed and to have the records of M.B.S. 3,50 B.P.S. 3,50 T.S. 3,50 A. Annual Survey 3,50

Generator fittings on main and sub-distribution boards examined, insulation resistance measured above and found efficient.

Main boiler examined internally and externally together with all mountings, manhole doors and their fastenings, all found or placed in efficient condition. Safety valves adjusted to pressure stated

and tested. Sea inlet and discharge valves, all now examined and found or placed in efficient condition.

Windlass engines, main condenser (tested), valves, struts and pipes of pumping arrangements examined pumps, general service and auxiliary feed pumps, independent circulating pump, dynamo, steering and brasses, main journals and bearings, thrust shaft, bearings, collars and liners, main engine attached Main engine covers, cylinders, valve chests, pistons, valves, rods, spindles, bottom end pins and screw shaft drawn and examined.

Vessel placed in dry dock, propeller, stern bush and sea connections, outside fastenings examined.

M.B.S. 3  
B.P.S. 3  
T.S. 3  
Elect. M.B.S. 3  
Ratings 3