

Report of Survey for Repairs, &c., of Engines and Boilers

20 JAN 1947

(Received at London Office)

Date of writing Report 10.1.47.

When handed in at Local Office 11.1.47.

Port of MARSEILLES.

No. in Survey held at Toulon & Marseilles.

Date, First Survey 10th Dec 46 Last Survey 8th Jan, 19 47.

Reg. Book.

(N^o of visits 1)71202 on the Machinery of the ~~Woolwich~~ Steel Screw Steamer "COLONEL VIELJEUX".Tonnage { Gross 7047
Net 4741

Vessel built at South Shields.

By whom J. Readhead & Sons Ltd. When 1944-8

Year. Month.

Nominal { 542
Horse Power }Engines made at D^o.By whom D^o.

When 1944

No. of Main Boilers 2

Boilers, when made (Main) 1944

(Aux. 1944)

No. of ~~aux.~~ Boilers 1

Owners French Government.

Owners' Address

(if not already recorded in Appendix to Register Book.)

Steam Pressure in Main Boilers 220 lbs

Managers Mlle. Cie. Havraise Péninsulaire.

Port Havre

Voyage

in ~~aux.~~ Boilers "

If Surveyed Afloat or in Dry Dock Both

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No.

Port

Particulars of Examination and Repair (if any)

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else. If so, by whom

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time

" " Donkey " " "

If this was not done, state for what reasons

And what parts of the Boilers could not be thus thoroughly examined

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler

To what pressure were they afterwards adjusted under steam

Did the Surveyor examine the Safety Valves of Donkey Boiler

To what pressure were they afterwards adjusted under steam

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boiler

Present condition of funnel(s)

Did the Surveyor examine the drain plugs of the Main Boilers

, and of the Donkey Boilers

Did the Surveyor examine all the mountings of the Main Boilers

, and of the Donkey Boilers

Has screw shaft now been drawn and examined

Is it fitted with continuous liner

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated

Has shaft now been changed

If so, state reasons

Has the shaft now fitted been previously used

Has it a continuous liner

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated

State date of examination of Screw Shaft

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and or power fitted

If so, did the Surveyor examine the generators, motors switchgear, cables and fuses

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

S R L. Centre boiler intermediate stop valve chest renewed, marked as follows Lr N°276 and it is assumed that this was supplied by the Engine Makers. The vessel's name should be removed from the SRL in respect to this.

Port and Starboard Boiler Superheaters.- A considerable number of element at combustion chamber ends found burned and thin. The repairs could not be completed before the vessel sailed and the Owners therefore decided to dispense with superheaters for one voyage, and on return to Marseilles, the elements will be replaced.

Temporary pipes have been fitted from Port and Starboard boiler main steps to main steam pipes leading to the main engine. New piping were tested to rule requirements and found

satisfactory. - Centre boiler main feed check valve replaced with one of double shut off type. This was examined and tested and found satisfactory and afterwards marked:

General Observations, Opinion, and Recommendation: Msl. 1/47 Lr D.A.M.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.&M.S. 9, 11, + L.M.C. 9, 11, or

+ LMC 140 lb., F.D., &c.)

CS 3, 34,

The machinery of this vessel, as far as seen, is in good and efficient condition and eligible, in my opinion to remain as now classed without fresh record of survey.

Survey Fee (per Section 29)

Frs. 5.000.-

Fees applied for

11.1. 19 47.

Special Damage or Repair Fee (if any)

Frs. 500.-

Received by me,

19

Travelling expenses (if chargeable)

FR. 14 FEB 1947

Committee's Minute

Assigned

Engineer Surveyor to Lloyd's Register of Shipping



Lloyd's Register
Foundation

008237-008247-0094

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required if so to be sent to