

Sunderland

23rd January, 1903.

John Lawrence & Frank Cook.

the Owners examine the 85 Magistrate  
1757 Loss Register, for the purpose of ascertaining  
the amount of damage stated to have been  
caused by striking against the dock wall  
in consequence of the breaking of a two  
and a half inch steel wire hawser when about  
to proceed to sea from South Dock, Sunderland  
18th January, 1903. For particulars see Log  
Book.

Found, when the vessel was lying  
afloat in South Dock, Sunderland, on 19th.  
January, the rudder, which is a built wrought  
iron rudder with single plate, very badly  
twisted over to port, the upper part of  
the rudder bent, top arm fractured, and a  
few rivets in the upper arm started and  
broken. On shifting the head steering  
gear it was found that with some  
difficulty the rudder could be bore order  
until the rudder quadrant was within five inches  
of the dock stop on port side, end over end over



starboard side.

Recommended, that a diver should be engaged to examine the stern frame and rudder gudgeons. (He reported that he could find no defects.) and that the rudder should be unshipped for further examination; to do so it was found necessary to split off the tiller of quadrant which is of wrought iron.

On 21st January, when at Sunderland Docks found the rudder very badly twisted and slightly out of line at about the upper arm.

Recommended the rudder to be renewed except the centre plate which is recommended to be fair'd and fitted to the new rudder.

Also, same date, attended on board the vessel and were present when the diver again examined the gudgeons and sternframe. (He reported that they were in good order.) A round spar would slightly less than the rudder's pintles which are four and a quarter inches in diameter was slipped down through the gudgeons without difficulty we are of opinion that the stern post is not bent.

Recommended the new rudder to be painted and shipped, the tiller to be renewed and fitted to quadrant, the hand steering gear and cover over same to be refitted, deck stuffing box and collar plate at lower part of rudder trunk to be refitted, the rods and chains of stern steering gear to be re-coupled up, the broken wire hawser to be renewed, and it is also recommended that the vessel be placed in Dry dock for examination on her return from her present voyage.

(Sgd) J. Lawrence

(Sgd) J. Cook.

© 2021



Lloyd's Register  
Foundation

0105 2/2

Fee £5·5·0

Dis 10% 11·0

Net. £4·14·0