

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report 7th October 1949 When handed in at Local Office 7th October 1949 Port of Grimsey
 No. in Survey held at Grimsey Date. First Survey 27th September last Survey 6th October 1949
 Reg. Book. 16722 on the Machinery of the Wood, Iron & Steel K 'LIMESLADE' (Shawler) (No. of Visits 1st)

Tonnage { Gross 290 Vessel built at Beverley By whom Lock, Welton & Gemmell Ltd When 1919-9
 Net 122 Engines made at Brith By whom Shaw & Chalmers When 1919
 Nominal { 87 HP Boilers, when made (Main) 1919 (Donkey) ✓
 Horse Power { 1.5E Owners Grimsey Lining & Shauling Ltd Owners' Address ✓
 No. of Main Boilers ✓ Managers Lindern Shawler Managers Ltd (If not already recorded in Appendix to Register Book.)
 No. of Donkey Boilers ✓ Port Grimsey Voyage Fishing
 Steam Pressure 180 lb
 in Main Boilers ✓
 in Donkey Boilers ✓
 Surveyed Afloat ✓ Fish Dock (State name of Dock.)

Last Report No. ✓ Port ✓

Particulars of Examination and Repairs (if any) B.S
 (Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler ✓ and make a thorough examination at this time? yes

" " Donkey " " " " ✓

If not, state for what reasons ✓ What parts of the Boiler could not be thus thoroughly examined? ✓

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of the Boiler? ✓

Date latest date of internal examination of each boiler 25th September Present condition of funnel(s) ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? yes To what pressure were they afterwards adjusted under steam? 180 lb / 10th

Did the Surveyor examine the Safety Valves of the Donkey Boilers? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? none fitted and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? yes and of the Donkey Boilers? ✓

Is the screw shaft now been drawn and examined? no Has it a continuous liner? ✓ Is an approved oil retaining appliance fitted at the after end? ✓

Is shaft now been changed? ✓ If so, state reasons ✓ Has the shaft now fitted been previously used? ✓ Has it a continuous liner? ✓

Is an approved oil retaining appliance fitted at the after end? ✓ State date of examination of Screw Shaft ✓ State the wear down in the stern bush Afloat

Is electric light and/or power fitted? ✓ If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Is the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

how done: Boiler examined internally and externally, safety valves, mountings, manhole doors and placed in good order, boiler later examined under steam and the safety valves adjusted as above.

Wear and Tear Repairs:- All plain tubes renewed in boiler, tube plates examined before retubing and found in order. Safety valve chest, top and bottom double shut off cocks for water gauge, steam valve to circulating pump, dynamo and deck removed and studs in boiler shell renewed, the double shut off cocks, circulating pump, dynamo and deck steam valve chests renewed. The new chests were tested hydraulically to Rule requirements before fitting and stamped as follows:-

Double shut off	Circ. pump	Dynamo	Deck
LLOYD'S 360 lbs 29.9.49	LLOYD'S 15 450 lbs 28.6.45	LLOYD'S S.W.S. 500 LBS 27.9.45	LLOYD'S NC 650 LBS 21.9.48

General Observations, Opinion, and Recommendation: The machinery is in good and efficient condition and
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, &MS 9,11 *LMC 9,11 or *LMC 140 lb., PD, &c.)
eligible in my opinion to remain as classed with a fresh record of BS 10-49

Survey Fee (per Section 23) BS £ 4 : 0 : 0 Fees applied for 7-10-1949
 Special Damage or Repair Fee (if any) £ : : Received by me, ✓
 Travelling expenses (if chargeable) £ : : 19

Committee's Minute FRL 11 NOV 1949

Signed BS 10.49

E. J. V. D. A.
 Engineer Surveyor to Lloyd's Register of Shipping.

