

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

FEB 28 1940

Date of writing Report 19th Feb 1940, When handed in at Local Office

21/2/1940

Port of

TRIESTE

No. in Survey held at

Trieste

Date, First Survey

6th Feb

Last Survey

15th Feb 1940

(No. of Visits 4)

Reg. Book.

31515 on the Machinery of the Wood, Iron or Steel S.S. "PERLA"

Tonnage Gross 5741
Net 3612

Vessel built at Pt. Glasgow

By whom

Clyde P.B. & Eng. Co.

When

Year. Month.

1926-1

Nominal Horse Power 468

Engines made at

By whom

(Donkey) ✓

When

No. of Main Boilers 3

Boilers, when made (Main) 1926

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port Venice

Voyage

No. of Donkey Boilers ✓

Managers

Steam Pressure in Main Boilers 200 lb/10"

If Surveyed Afloat or in Dry Dock

Afloat dry dock & afloat

in Donkey Boilers ✓

Last Report No.

Port

Particulars of Examination and Repairs (if any) B.S. & D.Rg.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? ✓

" " Donkey " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

State latest date of internal examination of each boiler

P-2, 40.

S. & C. Stated end. 11, 39

Present condition of funnel(s)

good

Did the Surveyor examine the Safety Valves of the Main Boiler? ✓

P. yes

To what pressure were they afterwards adjusted under steam? 205 lb/10" all

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

P. yes

To what pressure were they afterwards adjusted under steam? 3 boilers

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? ✓

P. yes

and of the Donkey Boilers? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Donkey Boilers? ✓

P. yes

and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? ✓

P. yes

and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? ✓

P. yes

and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? No

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓

If so, state reasons ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft ✓

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. 3/16"

Is electric light and/or power fitted? ✓

Engine parts, when referred to by numbers, should be counted from forward.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? ✓

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Complete, the starboard.

and centre boilers stated to have been examined at Port Said in 11, 39.

Now done:- The port boiler examined throughout together with

its principal mountings and all found or placed in good condition.

A local deflection of about 2" in the Centre furnace has been

packed up. A new whistle valve, examined and tested to

400 lb/10", has been fitted to the Centre boiler. The safety

valves of all three boilers were afterwards adjusted to 205 lb/10"

Docking - Vessel placed in dry dock. Propeller, after end

of stern bush and outside fastenings of sea connections

examined and found satisfactory.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0,11, B.&M.S. 0,11, L.M.C. 0,11, or 140 lb., E.D., &c.)

The machinery of this vessel, as now seen, is in

good condition and eligible in my opinion to remain as

classed with fresh record of B.S. 11, 39.

For Fees see

Survey Fee (per Section 29) £185-

Special Damage or Repair Fee (if any) £100-

Travelling expenses (if chargeable) £25-

Committee's Minute TUE 12 MAR 1940

Assigned

DUAL CLASS.

Received by me, 19

Engine Surveyor to Lloyd's Register of Shipping.

Lloyd's Register

Foundation

00847-00847-0199