

15. FEB. 1963

Ship's Name ~~xx~~/MS "HELGA SMITH"

Gross tons 2089

Is there a rpt. 9? Yes

Port Stockholm

Rpt. No. 14076

No. of visits 10

First date 8.1.63.

Last date 31.1.63.

Interim Cert. issued
& copy herewith?

Yes

Damage rpt. issued
& copy herewith?

Last rpt. (H.Q. only) 13782 - 8 Km.

Date of
completing rpt. 13.2.1963.

Surveyed at, if different from Port above Oskarshamn

Surveyed afloat
and/or in D.D. Both

Last date of examination in D.D. 28.1.1963.

Has a Load Line
Survey been held?

Yes

Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) (PS)

Survey fees Kr. 140:--

Damage fee

Kr. 1100:-- Expenses Kr. 770:--

Cond. of Class Kr. 100:--

S.A. fee -

I have surveyed the above ship in accordance with the Rules for DOCKING, DAMAGE AND CHANGE OF OWNERSHIP.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

DAMAGE REPAIRS NOW EFFECTED:- (Plates and frames numbered from aft).

Damage stated to have been sustained:-

- 1) By touching a sluice quayside at Montreal on the 5.6.1962.
- 2) By touching a sluice quayside at Wellington Dock, Liverpool, on the 14.7.62.
- 3) By touching a quayside at Toronto on the 24.8.62.
- 4) By heavy weather on a voyage Gothenburg-Montreal in October/November, 1962.
- 5) By touching a sluice quayside on a voyage Montreal-South Haven on the 6.11.62.
- 6) By touching a sluice quayside in Wellington Canal on the 30.11.62.
- 7) By touching a quayside at Montreal on the 3.12.62.
- 8) By touching a quayside at Gothenburg on the 23.12.62.

Continued overleaf.

I recommend that this ship remain as classed with/without ~~xxxx~~ fresh record of dry docking 1.63, without special conditions.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

FRIDAY 15 MAR 1963

Minute

15.1.63 without special.

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRI

POSTING

HEADER

CERT

Lloyd's Register
Foundation

008753-008758-0210/4

DAMAGE NO. 1.

Shell plating, port side.

K-strake, plate No. 1 (forecastle sheer) cropped and partly renewed.

Rail bulb faired in place.

Forecastle deck cropped and renewed in way.

Forecastle bulkhead faired in place.

DAMAGE NO. 2.

Shell plating, starboard side. (Aft hold).

F-strake, plate Nos. 6 and 7 faired in place.

G- " " " 6 faired in place.

G- " " " 7 and 8 removed, faired and refitted.

H- " " " 6,7 and 8 faired in place.

Shell plating, port side. (Aft hold).

G-strake, plate Nos. 6,7 and 8 renewed.

H- " " " 6 and 7 faired in place.

42 frames in way faired in place or repaired.

DAMAGE NO. 3.

Shell plating, starboard side. (Forward hold).

E-strake, plate Nos. 12 and 13 renewed.

F- " " " 11 and 12 removed, faired and refitted.

G- " " " 12 and 13 renewed.

H- " " " 12 and 13 faired in place.

E- " " " 14 renewed.

D- and F-strakes faired in place in way.

40 frames in way faired in place or repaired.

DAMAGE NO. 4.

Shelter deck, starboard side.

FOUND:-

A small crack in stringer plate between frames 80 and 81.

Continued.

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed or partly renewed.	14		2		
Removed and faired or replaced	4				
Faired or repaired in place	17	100	1		



© 2021

Lloyd's Register
Foundation

Rpt.

(cont.)

15. FEB. 1963

Ship's Name ~~SS~~/MS "HELGA SMITH"

Port Stockholm

Rpt. No. 14076

DONE:-

Stringer plate cropped in way and a new plate inserted by welding, abt.
1000 x 1000 x 12 mm.

Stern post.

Small cracks, port and starboard, in outer plate veed out and welded.

Bilge keel, starboard side.

5 rivets renewed at forward end.

DAMAGE NO. 5.

Shell plating, starboard side.

K-strake, plate No. 1 (forecastle sheer) faired in place.

Rail bulb in way faired in place.

Forecastle deck in way faired in place.

DAMAGE NO. 6.

Shell plating, port side (Forward hold).

F-strake, plate No. 12 renewed.

G- " " " 12 and 13 renewed.

H- " " " 12 faired in place.

E- " " " 14 renewed.

18 frames faired in place or repaired.

DAMAGE NO. 7.

Shell plating, starboard side.

I-strake, plate Nos 3 and 5 (bulwark) faired in place.

H- " " No. 6 faired in place.

DAMAGE NO. 8.

Stern.

Soft nose plate cropped and partly renewed abt. 2000 mm.

Repair hose tested.

CHANGE OF OWNERSHIP:-

The vessel now sold to Greek Owners.

Present name:- "HELGA SMITH"

Present homeport:- Piraeus.

Present Owners:- Messrs. Allseas Shipping Co., Geneva.

Present signal letters:- ~~XXXX~~ S Y R L.

CONDITIONS OF CLASS:-

NOTE 1:-

It is recommended the conditions regarding the forecastle deck, etc. (port aft corner) and the indented shell plating in E and F strakes in way of Nos. 1 and 2 holds should be deleted, same having now been permanently repaired.

Continued.

15. FEB. 1963

Rpt.

(cont.)

Ship's Name ~~SS~~/MS "HELGA SMITH"

Port Stockholm


Rpt. No. 14076

NOTE 2:-

S.R.L. Appendix No. 11, Page 78.

The wavy aft deck plating and the stiffened bottom plating with minor corrugations specially examined and the structure found to continue efficient.

We would kindly draw your attention to the fact that these defects should apply to "HELGA SMITH" and not to "HELDA SMITH", which ship does not exist in the Register.



© 2021

Lloyd's Register
Foundation

008753 - 008758 - 0210 3/4

15. FEB. 1963

Ship's Name ~~SS~~MS "HELGA SMITH"

S.S. () Due

Port Stockholm

Rpt. No. 14076

<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	8.1.1963.	* Air & sounding pipes	Good
" " " to	31.1.1963.	Doublers under " "	Not exd.
Shell plating	Good	Steering arrangements (main)	Good
Sternframe	Good	" " (aux)	Good
Rudder	Good	Windlass	Good
Was rudder lifted?	No	Masts & rigging	Good
Plating, etc. in way of shell openings	Not exd.	Hand pumps & suction	Not exd.
Side scuttles & deadlights	Not exd.	W.T. doors	Not exd.
Overbd. scuppers & discharges	Not exd.	Bulwarks, freeing ports, etc.	Good
F.P. spaces	Not exd.	Summer freeboard as verified	7.3/4" ✓
Chain locker	Not exd.		
A.P. spaces	Not exd.		
Engine space	Not exd.		
Boiler space	Not exd.		
Under E. & B.	Not exd.		
Coal bunker	None		
Tunnel & well	Not exd.		
Cement, asphalt, etc., on btm. shell	Not exd.		
Weather decks	Good		
* Casings	Good		
* Deckhouses	Good		
* Superstructures	Good		
* Skylights	Good		
* Companionways	Good		
* Hatchways	Good		
* Ventilators	Good		
Other items:	-		

EQUIPMENT:

Equipment letter	u
Fee ltr., if diff. from eqpt. ltr.	-
Anchors: No. on board	3 bowers
Cables {	State if ranged
	Length on board
	Mean dias. range from to
	Rule length Dia.
	Mooring ropes

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Surveyor to Lloyd's Register of Shipping

Foundation

008753 - 008758 - 0210 4/4

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	Good	F.P. tank	Not exd.	Not tested
"	'Tween decks	Good	A.P. tank	↓	↓
			D.B. tanks & c/dams		
No. 2	Hold	Good			
"	'Tween decks	Good			
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
			Settling tanks		
No. 4	Hold				
"	'Tween decks		Deep tanks		
No. 5	Hold				
"	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks	↓	↓
"	'Tween decks				
			Other tanks:		
	Cargo battens	Good			
	Ceiling, etc.	Good			



© 2021

Lloyd's Register
Foundation