

DISCLOSED

DISCLOSED

Received at London Office

24 AUG 1955

No. 2930

REPORT OF SURVEY FOR REPAIRS, &c.

No. 618 Date of writing Report 29th July, 1955. When handed in at Local Office 17. 1955. Port of KOBE

No. in Reg. Book 1521, 66014 Survey held at Osaka Date, First Survey 13th July, Last Survey 21st July, 1955. (No of Visits 6)

Built at Osaka By whom Fujinagata Zosen-sho K.K. When 1951 MONTH 9
GROSS 4979 Owners Inui Kisen K.K. Owners' Address
UNDER DK 4254 Managers
NET 3284 Port belonging to KobeSurveyed Afloat or in Dry Dock? Both Name of Dock Fujinagata S.B., Osaka Destined Voyage
Cell DBor DBa feet: uE&B feet: f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 2271 Port Kobe

Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form State also the dates and initials of any letters respecting this case

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?
REPAIRS, OR EXAMINATION AS PER RULE FOR Periodical Special Survey (A) Due 9,55 4 years old.

Now Done:- Ship placed in drydock. Shell plating, stern frame and rudder cleaned, examined and coated. Ship undocked on the 23rd July, 1955.

Examined:- All holds, 'tween decks, fore and after peak spaces, engine and boiler spaces, under engines and boilers, plating in way of sidelights, overboard scuppers and discharge pipes, decks with machinery and other casings, superstructures, skylights and companionways, hatchways, covers, supports, tarpaulins, cleats and battening arrangements, anchors, chain cables, chain locker, masts, rigging, steering gear, auxiliary steering gear, windlass, general equipment, pumps W/T doors, ventilator coamings and covers, air and sounding pipes (striking plate fitted) and cargo battens.

Freeboard verified. Rpt. Cl2(b) attached.

Examined (Internally) and tested:- Fore and After peak tanks, cant water ballast tank.
All double bottom tanks except No.5 double bottom tank. (P.T.O.)

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed ...								
Removed and Faird or Repaired								
Faird or Repaired in place				1				

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks Good	Good	Good	(State if on Felt.)
Caulking of Decks Good	Good	Coal Bunkers, Openings, Covers, &c. -	When fitted, Month Year
Coamings Good	Cement or Asphalt Good	Oil Bunkers -	
Beams & Fastenings Good	Rudder Good	Scuppers Good	Boats Good
Outside Plating Good	Steering gear and its connections Good	Cargo Hatchways Good	Masts, Yards, &c. Good
" " in way of sidelights Good	Windlass Good	Hatches Good	Condition, how ascertained from deck (State if wedges removed.) y
Frames Good	Have pumps been examined and found efficient? Yes	Planking	Equipment letter
Reverse Frames -	Have Sluice Valves been examined and found efficient? Yes	Caulking	Anchors, No. of 3B 1S
Longitudinals -	Have Watertight Doors been examined and found efficient? Yes	Troenalls	Cables (State if now ranged) Yes
Transverses Good	Have Ventilators and their Coamings been examined and found efficient? Yes	Breasthooks & Stems	" length 270 fms mean diamr. 2"
Floors Good	Air and Sounding Pipes Good	Transoms, Pointers & Crutches	" Rule length 270 fms size 1 7/8"
Keelsons -	Doubling Plates under Sounding Pipes Good	Timbers of Frame at openings	Chain Locker Good
Stringers Good		" " at other places	Hawser & Warps Sufficient
Inner Bottom Plating Good See Rpt.		Stringers, Clamps & Shelves	Standing and Running Rigging Efficient
Have the Tanks been examined internally? See Rpt.		Saltings	Sails
Have the Tanks been tested? See Rpt.		State if examined	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This Ship, so far as now surveyed, is eligible in our opinion to remain as now classed with record of docking 7,55 and to have the Notation of "S.S. Osa - 7,55" when the Special Survey is completed.

Survey Fee (per Section 23) 55/100% £7 104.000 Fees applied for, 19.
Special Damage or Repair Fee (if any) £ Received by me, 19.
Travelling Expenses (if chargeable) £ See Rpt. 9
Second Surveyor's Fee (if any) £

Committee's Minute

Character Assigned

THURSDAY 15 SEP 1955

7.55 Osa

DBS 7.55

Surveyors to Lloyd's Register of Shipping.

© 2021

Lloyd's Register Foundation

008773-008777-0046

Is Certificate required? If so, to be sent to

spaces cleaned as required.

spaces cleaned as required.

Steel Work afterwards coated as necessary and ceiling, lining and cement replaced.

in way of keel plates

Nos. 2 & 3 from for'd port and starb'd.

Slight fracture in tank top plate in way of end of engine girder extension in

No.3 D.B. tank now cropped and partly renewed in thicker plate.

Reinforcement:- By Owner's request, 6" inverted angle, have now been fitted by

enforcement:- By Owner's request, O invested along with
welding to bottom shell plating in No.2 double bottom tanks on line of full and
..... (shaded plan)

half fore and aft intercostal girders. (See attached plan).

Alteration:- No.2 steel hatch covers have now changed to wooden hatch covers.

Operation:- No.2 steel hatch covers have now been
Hatch construction rebuilt as per approved plan attached. The original hatches

of Macgregor Type had not proved W.T. in service.

To Complete Special Survey:- No.5 double bottom tank to be examined internally and tested.

Interim Certificate No. B1-24151 issued - copy attached.

Rpt. 14 attached herewith.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

ANCHORS.																	
Number of Certificate.	Anchors.*	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream																
	Kedge																

<

* When a bowler anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bowler.

CHAIN CABLES.

[illegible]

..... If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN