

# Report of Survey for Repairs, &c., of Engines and Boilers.

No. 47389

Date of writing Report Oct. 14th 1946 When handed in at Local Office Oct. 14th 1946 Port of NEW YORK  
 No. in Reg. Book 85188 Survey held at New York Date, First Survey and Last Survey Oct. 7th 1946  
 on the Machinery of the Wood, Donkey Steel S.S. "WILLIAM LUCKENBACH" (No. of Visits 1)

Tonnage { Gross 6939  
 Net 4012 Vessel built at Vegesack By whom Bremer Vulkan Year. Month. 1913  
 Nominal Horse Power 890 Engines made at Vegesack By whom Bremer Vulkan When 1913  
 No. of Main Boilers 5 Boilers, when made (Main) 2 Fwd MADE 18 REFITTED 34 (Donkey)  
 No. of Donkey Boilers — Owners Luckenbach S.S. Co., Inc. Owners' Address —  
 Steam Pressure in Main Boilers 220 lbs. Managers — (if not already recorded in Appendix to Register Book.)  
 in Donkey Boilers — If Surveyed Afloat or in Dry Dock Drydock Port New York Voyage —  
 (State name of Dock.) Todd Shipyards Corp. Brklyn

Last Report No. — Port —

## Particulars of Examination and Repairs (if any) Fastenings

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom? —

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? —

" " Donkey " " " "

If this was not done, state for what reasons? Not due for survey.

And what parts of the Boilers could not be thus thoroughly examined? —

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? —

State latest date of internal examination of each boiler. —

Did the Surveyor examine the Safety Valves of the Main Boiler? — Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of Donkey Boiler? — To what pressure were they afterwards adjusted under steam? —

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? — and of the Donkey Boilers? —

Did the Surveyor examine the drain plugs of the Main Boilers? — and of the Donkey Boilers? —

Did the Surveyor examine all the mountings of the Main Boilers? — and of the Donkey Boilers? —

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? — Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —

Has shaft now been changed? — If so, state reasons —

Has the shaft now fitted been previously used? — Has it a continuous liner? — Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? —

State date of examination of Screw Shaft — State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft 5/32"

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and/or power fitted? Yes

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? —

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? —

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Now Done:- Vessel placed in drydock, propeller, aft end of stern bush, shell fastenings of sea connections examined and found in order.

Wear & Tear:- Holes drilled at ends of small cracks on 3 bronze propeller blades, cracks vee'd out and brazed.

General Observations, Opinion, and Recommendation:— The machinery and boilers of this vessel are in good condition and eligible in my opinion to remain as classed without fresh record.  
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.E.M.S. 9,11, \*L.M.C. 9,11, or \*L.M.C. 140 lb., F.D., &c.)  
 \*L.M.C. 140 lb., F.D., &c.)  
 CS 3,34,

Survey Fee (per Section 29) \$ : : Fees applied for 19  
 Special Damage or Repair Fee (if any) \$ : : Received by me, 19  
 (per Section 29.)  
 Travelling expenses (if chargeable) \$ : : —

Committee's Minute NEW YORK OCT 16 1946

Assigned As now

M. S. Keeler  
 Engineer Surveyor to Lloyd's Register of Shipping.



N Ned

9.5.

19.11.46

Boiler has been repaired by Engineer and Boilers

© 2021

Lloyd's Register Foundation

