

250,914.

*Dire 751*

F.E.

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel S.S. "CAMILLA GILBERT" Rpt. Nw. No. 72986

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. 80.08 Depth "d" 23.34

Framing: Table No. 3 page 6 Description Bulb angle as approved

Longitudinal No. 31999

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  11.2

Shelter  
Deck Sheerstrake as approved.

*The Downhaul Pump has been dispensed with for the present.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~as~~ 100 A.1. (steel) "Shelter Deck with freeboard," as recommended. The Summer freeboard of 9'-5" from centre of disc to top of statutory deck line at Shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 Dk (steel) & Shelter Dk. (steel)

Cell DB 351 1178 t. ; FPT 60 t. APT 80 t.

FK. 2 BH to Shelter Dk 5 BH to upper Dk. Pt. cem. Lloyd's A.C.P. For Shelter Dk. 37'.

The Certificate of Classification, to be endorsed in Tween Dks. "Cargo battens not fitted," and the same notation to be printed in the Register Book.

Lloyd's Register Foundation  
M  
AES  
16-4-20  
008839-008846-0298

BEAMS, POOP DECK  
Tee Bu  
Angles on