

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

(Received at London Office

8- APR 1949

ABERDEEN

Date of writing Report 6/ 4/ 49

When handed in at Local Office 6/ 4/ 49

Port of

No. in Survey held at ABERDEEN

Date. First Survey

and

Last Survey

2nd April 1949

Reg. Book.

52157 on the Machinery of the Wood, Iron or Steel

S. T. "AVOLA"

(No. of Visits)

Gross 255

Vessel built at Middlesbro

By whom

Smith's Dock Co Ltd.

When

1913

Month

6

Tonnage { Net 99

Engines made at Do.

By whom

Do.

When

"

"

Nominal Horse Power 100 MN

Boilers, when made (Main) 1928.

(Donkey)

No. of Main Boilers One

Owners Joseph Craig, Ritchie (Filling) Ltd

Owners' Address

No. of Donkey Boilers Nil

Managers

Joseph Craig

Port

Aberdeen

Voyage

Steam Pressure 180 lbsq

If Surveyed Afloat or in Dry Dock

Afloat

in Main Boilers

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.

Years assigned now expired.

Machinery and Boiler Surveys (including date of N.B., if any)

+100 A1

Steam Trawler

M, 49 3.49

Reclassified 3, 46

S.S. Abdn. 2nd

No 3-3, 46

L.M.C. 3, 46

E.S. 3, 47

N.B. made 28

refitted 47.

T.S.C.L. N.

3.49

3, 46.

Last Report No. 22592. Port Abn.

Particulars of Examination and Repairs (if any)

Compl B.S.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " "

If not, state for what reasons

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under steam? 180 lb sq "

Did the Surveyor examine the Safety Valves of the Donkey Boilers?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

and of the Donkey Boilers?

Has the screw shaft now been drawn and examined?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed?

If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end?

No

State date of examination of Screw Shaft

State the wear down in the stern bush

Is electric light and/or power fitted?

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Complete

Now done. Examined boiler under steam and safety valves adjusted as stated above.

Note.

The screw shaft will be drawn when the vessel is next dry docked within a few months.

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, ES 3,11, B&MS 3,11 or LMC 3,11 or LMC 140 lb., FD, &c.)

CS 3,34.

The machinery of this vessel is eligible, in my opinion, to remain as classed and to have record of B.S. 3,49.

Survey Fee (per Section 29) £ : :

Fees applied for

19

Special Damage or Repair Fee (if any) £ : :

(per Section 29.)

Received by me,

Travelling expenses (if chargeable) £ : :

19

Committee's Minute

TUES. 26 APR 1949

Assigned

As met

(subject to amended)

Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

008900-008908-0065

Abn 21/3



*Safety valves readjusted.*

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**.

*L.F.  
23/6/49.*



© 2020

Lloyd's Register  
Foundation