

16 SEP 1949

No. 3126

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 5/8 1949 When handed in at Local Office 5/8 1949 Port of GDYNIA
No. in Survey held at GDYNIA Date, First Survey 1st Aug. Last Survey 22nd Aug. 1949
Reg. Book 15280 on the Wood/Iron/Pl/Steel S.S. "KILINSKI" (No. of Visits 7)

TONNAGE:— Built at Los Angeles, Cal. By whom California S.B. Corp. When 1944 MONTH.
GROSS 7612 Owners Gdynia-America Shipping Lines Ltd. Owners' Address —
UNDER DEK 6771 (If not already recorded in Appendix to Register Book)
NET 4555 Managers — Port belonging to Gdansk

Surveyed Afloat or in Dry Dock? Both Name of Dock Indian Quay & No. 1.D.D. Destined Voyage —

Cell D B or D Ba — feet; uE & B — feet; f — feet
total capacity — tons. FPT — tons; APT — tons; MT — feet — tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. — Port —

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined No damage

Was a damage report made by anyone else? if so, by whom? —

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking & Part S.S. (Vessel undocked 15th Aug. 1949)
Now done:— Cert.B issued, copy attached.

Load Line Renewal Survey carried out.

Docking:— Vessel in drydock, bottom and rudder cleaned, examined and found or placed in satisfactory condition and recoated.

Weather decks, casings, coamings, hatchways with their closing appliances, ventilators, windlass, steering gear, storm valves, and General Equipment examined and found or placed in satisfactory condition.

The following plates (numbered from forward) were found to be slightly set in between frames:—

Port side A4 and A5

Starboard side: A4, A5 and B5.

Keel plates: Nos. 3 and 4.

P.T.O.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired	/ / / / /	/ / / / /	/ / / / /	/ / / / /	/ / / / /	/ / / / /	/ / / / /	/ / / / /
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Pt. Ex. Satisfy.	Engine Room Skylights	Good	Copper, or Y.M.
Decks Satisfactory	Ceiling do		Coal Bunkers, Openings, Covers, &c. —		(State if on Felt.)
Caulking of Decks do.	Cement or Asphalt —		Oil Bunkers —		When fitted, Month Year
Coamings Good	Rudder Good		Scuppers Good		Boats —
Beams & Fastenings Good	Steering gear and its connections Good		Cargo Hatchways Good		Masts, Yards, &c. Satisfy.
Outside Plating Satisfactory	Windlass do		Hatches Good		Condition, how ascertained from dk.
" " In way of sidelights do	Have pumps been examined and found efficient? —		Planking		(State if wedges removed.)
Frames Pt. Ex. Satisfy.	Have Sluice Valves been examined and found efficient? —		Caulking		Equipment letter c +
Reverse Frames do	Have Watertight Doors been examined and found efficient? Yes		Treenails		Anchors, No. of 3 B 1 S
Longitudinals —	Have Ventilators and their Coamings been examined and found efficient? Yes		Breasthooks & Stemson		Cables (State if now ranged) No
Transverses —	Air and Sounding Pipes Pt. Ex. Satisfy		Transoms, Pointers & Crutches		" length stated complete
Floors Pt. Ex. Satisfy.	Doubling Plates under Sounding Pipes do.		Timbers of Frame at openings		" (on board.) mean diamr.
Keelsons do			" " at other places		" Rule length 300 size 2 1/2
Stringers —			Stringers, Clamps & Shelves		Chain Locker —
Inner Bottom Plating Pt. Ex. Good			Salting State if examined.		Hawsers & Warps Sufficient
Have the Tanks been examined internally? Part					Standing and Running Rigging Efficient
Have the Tanks been tested? Part					Sails —

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, so far as now seen, is eligible in my opinion, to have fresh Record of Survey 8,49 now,

and S.S. Gdynia (with date) when No. 4 Centre D.B. tank has been examined, subject to set in Nos. 3 and 4

(from forward) keel plates, and port and starboard plating in way, being specially examined at next drydocking,

Anchors and cables to be verified with Certificates, and without special conditions re Tunnel W.T. door and

Endorsement, wavy bottom plating amidships.

Survey Fee (per Section 29) — Condition 41. 16,120.

Special Damage or Repair Fee (if any) — Fees applied for, 5/9 1949

Travelling Expenses (if chargeable) — Received by me, 1,350 not yet 19

Second Surveyor's Fee (if any) —

Committee's Minute —

Character Assigned —

J. A. Bouter © 2020

Surveyor to Lloyd's Register of Shipping.

WED. 1 MAR 1950

Deferred

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.