

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 4/8 1948 When handed in at Local Office... 4/8 1948 Port of... GDYNIA
 No. in Survey held at Gdansk Date, First Survey 7th July Last Survey 20th July 1948
 Reg. Book. 37211 on the Wood/Iron/Steel S.S. "KILINSKI" (ex "Mexico Victory") (No. of Visits... four)

TONNAGE:— Built at Los Angeles, Cal. By whom California S.B. Corp. Los Angeles When 1944
 GROSS 7612 Owners Gdynia-America Shipping Lines Ltd. Owners' Address
 UNDER DK. — Managers — Port belonging to Gdansk
 NET 4555

Surveyed Afloat or in Dry Dock? both Name of Dock Gdansk Destined Voyage —
 Cell DBor DBa — feet; uE & B — feet; f — feet
 total capacity — tons. FPT — tons; APT — tons; MT — feet — tons.

Only alterations in the existing records of tanks should be inserted.
 N.B.—All alterations in the existing records should be underlined.

Last Report, No. — Port —

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined — Society's Freeboard (if assigned) as painted on Ship and now verified } — ft. — ins.

Was a damage report made by anyone else? if so, by whom? —
 REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking, Part Classification, Freeboard renewal survey.

Now done:—
Docking: Vessel examined in drydock, shell plating and rudder cleaned, examined and coated. Very slight deflections to bottom plating half length amidships were noted, found efficient, not considered detrimental. ✓ Gne 1888
Examined:— Holds, decks, 'tween decks, Engine and boiler spaces, under engines and boilers, chain locker, anchors and cables, fore-peak tank internally, fore-peak spaces, after-peak tank, internally, after-peak spaces, plating under sidelights, hatchways, covers, supports, tarpaulins, cleats and battening arrangements air and sounding pipes where applicable, masts, rigging, windlass, steering gear, ventilators, W.T. door, equipment, freeboard and boats.
 Ceiling removed as required. All D.B. tanks, deep tanks, fore and aft peak tanks tested.
Note Tunnel W.T. door found to be hinged type. Owners representative stated that approved sliding door will be fitted end of present voyage.
 To complete the survey all D.B. tanks and deep tanks remain to be examined internally: approved tunnel sliding door to be fitted vide Circular No. 1871.

Internal examination of the tanks used for oil fuel not considered necessary. See letter 9.12.48

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired	////	////	////	////	////	////	////	////
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Good	Bulkheads	Good	Engine Room Skylights	Good	Copper, or Y.M.	—
Decks	"	Ceiling	"	Engine Bunkers, Openings, Covers, &c.	"	(State if on Felt.)	—
Caulking of Decks	"	Cement or Asphalt	—	Oil Bunkers	"	When fitted, Month	—
Coamings	"	Rudder	Good	Seuppers	"	Boats	Efficient
Beams & Fastenings	"	Steering gear and its connections	Good	Cargo Hatchways	"	Masts, Yards, &c.	Good
Outside Plating	"	Windlass	"	Hatches	"	Condition, how ascertained from deck	none
" " In way of sidelights	"	Have pumps been examined and found efficient?	—	Planking	—	(State if wedges removed.)	none
Frames	"	Have Stulce Valves been examined and found efficient?	—	Caulking	—	Equipment letter	C +
Reverse Frames	"	Have Watertight Doors been examined and found efficient?	Yes ✓	Treenails	—	Anchors, No. of	3 Bower 1 stream
Longitudinals	"	Have Ventilators and their Coamings been examined and found efficient?	Yes ✓	Breasthooks & Stemson	—	Cables (State if now ranged)	Yes
Transverses	"	Air and Sounding Pipes where Exmd. Good	✓	Transoms, Pointers & Crutches	—	" length 300 ✓ mean diam. 2 1/16"	(on board.)
Floors where exmd. Good	✓	Doubling Plates under Sounding Pipes	—	Timbers of Frame at openings	—	" Rule length — size —	—
Keelsons	—			" " at other places	—	Chain Locker	Good
Stringers where exmd. Good	✓			Stringers, Clamps & Shelves	—	Hawsers & Warps	Sufficient
Inner Bottom Plating	Good			Salting	—	Standing and Running Rigging	Efficient
Have the Tanks been examined internally? No	—			State if examined.		Sails	—
Have the Tanks been tested? Yes	✓						

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, where now seen, is in good condition, and eligible in my opinion to have record of Survey 7.48, and to be classed 100 A 1 on completion of the Survey, subject to existing tunnel W.T. door being replaced by approved door.

Part Classification	328,000	Fees applied for,	
Survey Fee (per Section 29)	£ 16,000	19	
Special Damage or Repair Fee (if any) (per Sec. 29)	£ :	Received by me,	
Travelling Expenses (if chargeable)	£ 20,000	19	
Second Surveyor's Fee (if any)	£ :		

Committee's Minute. ✓
 Character Assigned. ✓
 See minute in file

FRI. 29 OCT 1948

L. V. Hansen

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

008909-008916-0161