

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 14 JUN 1926)

Date of writing Report	5/3/1926	When handed in at Local Office	5/3/1926	Port of Sydney N.S.W.
No. in g. Book.	Survey held at Sydney N.S.W.	Date, First Survey	31/3/26	Last Survey 28/4/1926 (No. of Visits 5)
1390 on the Machinery of the Wood, Iron or Steel	Gross 5262	Master		YEAR. MONTH.
Net 3219	Vessel built at Geestemünde	By whom J. C. Tickler long A.G. When 1905 11		
registered Power 594	Engines made at Geestemünde	By whom J. C. Tickler long A.G. When 1905		
of Main Boilers 3	Boilers, when made (Main) 1905	(Donkey) (aux.) 1905		
of Donkey Boilers 1	Owners Australian Commonwealth Line of Ships Port London	Voyage U.K. via ports.		
Steam Pressure— Main Boilers 220 lbs	If Surveyed Afloat or in Dry Dock Cockatoo Dry Dock and Particulars of Classification (which must be inserted (State name of Dock) afloat in Sydney Harbour	precisely as in Register Book & Supplements.		
and Donkey Boilers 220 lbs				

Last Report No. Port

Particulars of Examination and Repairs (if any) 4.19.C. and Propeller Shaft

"when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of which must be stated) should be separated from Repairs due to other causes; and added in the body of the report, should be briefly summarised at the end of the report. State also the cause of any letters respecting this case."

where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were not accepted.

Was a damage report made by anyone else? If so, by whom?

Personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " "

yes.

State for what reasons?

yes.

the Boilers could not be thus thoroughly examined?

v

means, in the absence of internal examination, were adopted by the Surveyor himself of the thorough efficiency of those parts of each Boiler?

v

Examine the Safety Valves of the Main Boiler?

yes.

To what pressure were they afterwards adjusted under steam?

220 lbs.

Examine the Safety Valves of Donkey Boiler?

yes.

To what pressure were they afterwards adjusted under steam?

220 lbs.

Examine all the manholes, doors and their fastenings of the Main Boilers?

yes.

, and of the Donkey Boiler?

yes.

Examine the drain plugs of the Main Boilers?

, and of the Donkey Boiler?

Examine all the mountings of the Main Boilers?

yes.

, and of the Donkey Boiler?

yes.

now been drawn and examined?

yes.

Is it fitted with continuous liner?

yes.

or two liners?

or is it without liners?

v

been changed? No. If so, state reasons

v

fitted new?

Has it a continuous liner?

v

or two liners?

v

or is it without liners?

v

the between lignum vitæ of stern bush and top of after bearing of screw shaft?

3/16

not complete state what arrangements have been made for its completion and what remains to be done?

Complete.

vessel placed in dry dock, propeller shaft drawn inward, examined and in good condition, stern bush not renewed, propeller good. All sea valves and discharges opened out, examined, found good.

engines opened out, cylinders, pistons, rings, rods, valves and chambers, crank and tunnel shafts, with shims and bearings examined, found good.

opened out, examined, found good. Condenser opened out, 15 tubes found old, renewed, condenser tested and found sound and tight. Ruses and

examined, found clear, pumps tried on bilges and found in order.

water opened out, examined internally and externally with mountings and in good condition. Evaporator seen under steam, found tight, safety adjusted and blowing freely at 20 lbs. per sq. inch. Spare gear checked and found in order.

Port, Centre and Star. Main boilers and auxiliary

Observations, Opinion, and Recommendation:

any alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9/11, B.M.S. 9/11, or X.L.H.C. 9/11, 1lb., E.D., &c.)

vessel's machinery is now in good condition, eligible in my opinion main as classed, with record of + L.M.C. 4-26 and Propeller Shaft Seen 4-26 in the Register Book, subject to the main boiler furnaces being examined the end of October 1926.

per Section 28) £21.0.0 Fees applied for
ge or Repair Fee (if any) £ : : 3/5/1926
per Section 28.) £ : :
xpenses (if chargeable) £ : : Received by me,
19

TUES. 19 OCT 1926

Jas. C. Escombe
Engineer Surveyor to Lloyd's Register of Shipping.

tee's Minute

FRI. 18 JUN 1926

TUES. 9 NOV 1926

TUES. 30 NOV 1926

CERTIFICATE WRITTEN

009341 - 009349 - 0273

Insert character of ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

Lloyd's Register Foundation

S. S. No 2 due 4. 26 now
held & insurance due if
it is submitted
this vessel is fit for
THE RECORD & LMC 4. 26.
S 4. 26. Subject to the
main boiler furnaces
being examined before
the end of October 1926.
J.W.D.
17/6/26

You by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side

boiler opened out, cleaned, examined internally and externally with mountings and found in good condition except in centre boiler 4 C.C. stay nuts burnt and in star'd boiler 3 C.C. stay nuts burnt, all renewed and now good, all main boilers furnaces out of true circle, ganged, found still good but should be examined before the end of October 1926. In limit list:- "Examine M.B. furnaces, 6 mos. 2-26." Main boiler furnaces now examined as above.

Port, centre and star'd main boilers and auxiliary boiler seen under steam, found tight, safety valves adjusted and blowing freely at 220 lbs. per sq. inch.

Main engines seen working in order under steam.

OR THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021
Lloyd's Register
Foundation