

No. 61916

(Received at London Office 17 JAN 1940)

Date of writing Report 9th Jan 7 40 When handed in at Local Office 13. 1. 40 Port of Glasgow
 No. in Reg. Book. 29941 Survey held at Glasgow Date, First Survey 26th Dec. Last Survey 27th Dec. 1939
 on the Machinery of the Wood, Iron or Steel Twin Sc "MONTCALM"
 (No. of Visits 2)
 Tonnage { Gross 16418 Vessel built at Glasgow By whom J. Brown & Co. Ltd Year. Month.
 Net 9789 Engines made at Belfast When 1921-12
 Nominal Horse Power { 2390 By whom Harland & Wolff Ltd When 1929-3
 No. of Main Boilers 10 SA Boilers, when made (Main) 1921 (Donkey) -
 Owners Canadian Pacific Railway Co. Owners' Address -
 No. of Donkey Boilers 1 Managers Canadian Pacific Steamships Ltd (if not already recorded in Appendix to Register Book.)
 Steam Pressure— 215 lbs Port Liverpool Voyage -
 in Main Boilers 222 lbs If Surveyed Afloat or in Dry Dock Elder's dry dock
 in Donkey Boilers - (State name of Dock.)
 Particulars of Classification (which must be inserted)

Last Report No. *Port*

Particulars of Examination and Repairs (if any) *docking, T.S.*
(Periodical Surveys, when held, must be reported in detail and certified by the Surveyor.)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *No*

" " Donkey "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Did the Surveyor examine the Safety Valves of the Main Boiler?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

Has screw shaft now been drawn and examined? Parting Is it fitted with contingous liner?

Has shaft now been changed? No If so, state reasons

Has the shaft now fitted been previously used?

State date of examination of Screw Shaft 27.12.39

Engine parts, when referred to by numbers, should be counted from forward.

^ so, did the Surveyor examine the generators, motors, switchgear, cables and fuses ?

has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done Complete

Vessel placed in dry dock. Propeller, and Sea Connections, with their fastenings examined. Port Tail Shaft drawn, examined, now in safe working order.

S.R.L. No 5 Boilers Main stop Valve chest now renewed (see attached certificate)
No opportunity afforded to examine repairs to back end plate of this Boiler under Steam.

Survey carried out at owner's request. This vessel has now been chartered to the Admiralty.

206
13/1/40

General Observations, Opinion, and Recommendation:—*The machinery, so far as seen, is in*
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 2, 11, S.M.S. 2, 11, X L.M.C. 2, 11, or
X L.M.C. 140 lb., F.D., &c.)
CS 2, 31,
reps working condition and it is recommended that the record of Port Tail Shaft seen
(L.L.) 12.39 be made in the Register Book. Test Steam pipes at B.O.T. Survey. No 5 Boilers
not to be used until repairs to back end plate specially examined under steam. (Delete from S.R.
No 5 Boilers not to be used until Main Stop Valve chest renewed.)

Survey Fee (per Section 29).....	£	:	:	Fees applied for
				19
Special Damage or Repair Fee (if any).....	£	:	:	
(per Section 29.)				
Travelling expenses (if chargeable).....	£	:	:	Received by me,
				19

Committee's Minute **GLASGOW** 16 JAN 1940

Assigned is now subject
72.39(x)

12.39 (h)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER, * for Special Survey Date of last Survey and of Periodicals Surveys.	Years assigned how extnd.	Machinery and Bolter Surveys (including date of N.B., if any).
+ 100 A.I. Shells		+ L.M.C. 2.37
all with fuses.		+ N.E. 3.29
4.39		B.S. 3.39
SS in NE3 - 12.33.		TS (C.L.) P 1.37
SS Box No 1 - 38.		S. 3.39
putted for oil fuel		12.21. F. Palmer
		150°

Special note
in G.R.L.

B. H. Macdonnell © 2021
Engineer Surveyor to Lloyd's Register of Shipping

Lloyd's Register
Foundation

009522-009526-0076