

Date of writing Report.....19.....When handed in at Local Office.....19.....

Port of Lyttleton

No. in Survey held at Lyttleton Date, First Survey Sept. 22 Last Survey 6th. Oct. 1924

Reg. Book. (No. of Vessels)

79181 on the ~~Wood, Iron or Steel~~ S.S. Orepuki' Master

By whom Google S.B. Reg. Co. Ltd. When 1908 7

UNDER/DK. 378 *Pennsylvania Co., Inc. (Heese Bros), Port belonging to Lytleton*

(if not already recorded in Appendix to Register Book).

$WB = CellDB \text{ or } DBa$ 32 feet; $uE \& B$ feet; f feet:)

N.B.—All alterations in the existing records should be underlined.

girders, and of the inner bottom plating, especially in the boiler space.		Periodical Surveys.	TH	CH	(Including date of N.B., if any).
I D M L S B		A1			

Tail shaft

on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the book, should be entered in the following manner:

the back of this form. State also the dates and initials of any letters respecting this case. *Re 15th July. painted on Ship and now verified*ft.....ins

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were

REPAIRS OR EXAMINATION AS PER RULE FOR Second 57 and 1.5

Plating Inside and Outside Holds, Peaks & Bunker-space, Engines, Boiler-space and accomodations.

space examined and found in good order. All ceilings and limber boards in Holds and Bunkers were

for examination. Vessel's bottom and outside plating, minimum thickness $\frac{3}{8}$ amidships and $\frac{5}{16}$ at

...all the buildings and structures have been scaled and painted. Bunkers have been

...more regular, tank tops asht na

Tanks have been cleaned and pumped out and are to be used for

framing, and girders is good. There is no D B under Engine and Boiler room.

The Rudder has been lifted and Pintles re-bushed and tightened up

Steering-gear, Leads, Quadrant, and Quarter-Blocks have been overhauled and New lines supplied when

SUMMARY OF DAMAGE REPAIRS :—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items.	P.T.O.
------------------------------	---------	---------	------------	---------	--------	--------------	-------------	--------------	--------

Removed and Faired or Repaired	(Deck Plate Port side Stokenhold Eildley renewed 61 x 51 3/4" = 3"	South
--------------------------------	--	-------

PRESENT CONDITION OF THE Stringers Good

.....
 bulking of Decks..... Good State if Tanks have been examined inside Yes
 Engine Room Skylights..... Good When put on, Month..... Year.....

Names	Good	Bulkheads	Good	Scuppers	Good	Masts, Yards, &c.	Good
-------	------	-----------	------	----------	------	-------------------	------

Roofs & Fastenings	Good	Hatches	Good
Outside Plating	Good	Cement or Asphalt	Asphalt
			below N

Steering gear and its connections Good

Fasthooks & Crutches.....	600	Have Pumps now been examined and found effi-	Breasthooks & Stemson	ditto.....	Anchors, No. of

Have Sluice Valves now been examined and found

Goad		Stringers, Clamps & Shells	ditto.....	
Have Watertight Doors now been examined and found		Satisfactory		Hawser & Warps..... Sufficient

General Observations. At 11:00 AM, the sky was clear and the temperature was 65°F. The wind was light and variable. The water was calm and the tide was low.

this survey, thus, for example:—"..... to remain as now classed in the Register Book, and no alteration of the vessel in the Register Book consequent upon

Special Damage or Defect: None

Received by me, *104*

and Surveyor's Fee (if any) £ : X : *Adm* Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character Assigned 10071

8. 8. No. 1-24

0049551-609569-0031

1

Winlass The threads carrying the brake nuts at Port and Starboard Sides of the Main Shaft were broken and worn and I recommended a new shaft. This was supplied and fitted in. The Winlass has been taken ashore to the repairing shop and thoroughly overhauled and new Brake Nuts have also been fitted to Main Shaft.

Winches have been stripped and examined and put into good working order. Cargo derrick fastenings have been overhauled. All hatch combings, Bulwarks, and Decks have been scaled and tarred.

Hold Stanchions have been reriveted where required.

Cables and Cable-fastenings have been examined and found in order.

Chain-Locker cleaned out and tarred.

Steering-engine tested under steam at completion of survey.

ANCHORS.

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

Lloyd's Register
Foundation