

"S.S. DAINITI MARU"

Repairs due to wear & tear:-

H.P. top half crank brass retailed.
L.P. piston rod skimmed up, neck and gland bush renewed.
Inboard feed pump water cylinder renewed, new water cylinder tested by an hydraulic pressure to double the working pressure and found good.

P. boiler:- 1 small stay renewed.
O. boiler:- Main check valve box renewed, The new box was hydraulically tested by 2 x W.P.
S. boiler:- 7 small stays renewed.

Other minor repairs and adjustment effected. *huk*

Exp. Examined

*It is submitted that
this vessel is eligible for
THE RECORD. Folio 1040*

*No 2 due 0.40 - so complete.
Examiner test steam pipes
electrical rigging.
Subject as recommended*

20/9/41



© 2020

Lloyd's Register
Foundation