

Two (2) main feed pumps portside forward E.R.

Two (2) general service pumps, ps.s. aft E.R. bulkhead.

Main circulating pump and engine ps E.R.

Forced draught blower and engine Starboard side E.R.

Sanitary pump, p.s. forward E.R. Evaporator opened examined and tested, safety valves adjusted.

Feed water heater p.s. upper E.R. examined and tested.

Auxiliary condenser combination air and circulating pump Starboard side E.R.

Fuel oil transfer pump. Two (2) fuel oil service pumps, forward bulkhead.

Three (3) 20 K.W. generators and engines starboard side generator flat.

Machinery repairs:-

M.P. Matchbox valve found badly worn at sides, valve and cage removed to shop, valve machined at sides and cast iron wearing strips fitted, valve cage machined to true surface and proper clearance, replaced in good order.

Main throttle valve; found valve and seat badly cut, also governor butterfly slack on stem. Valve removed to shop, valve disc and seat machined, butterfly valve refitted, valve tested under steam 300 lbs. and replaced in good order.

Main circulating pump: Upper half casing removed to shop and cast iron sheel fitted in way of after stuffing box, casing replaced in good order.

Main feed pumps, suction and delivery, valves refitted seam and liquid end rings renewed.

Fuel oil transfer pump liquid end rings renewed.

Generator engines governor gear overhauled and placed in good order.

Inboard generator engine piston valve renewed.

Generators cleaned and recoated, brush gear refitted.

Bottom blow shell valve spool piece found badly worn, renewed complete.

Auxiliary condenser air pump piston rod removed to shop, rod machined and gland and neck ring bushes renewed.

After bilge suction line in shaft tunnel valve stem and disc renewed.

The two (2) main W.T. boilers were examined over all parts with doors, mounting and safety valves and found or placed in good order.

Safety valves adjusted under steam as stated.

Fuel oil burning system with installation of valves, piping, and duck control examined under working condition and found satisfactory.

Boiler repairs:- All hand hole covers removed, tubes turbinized and all hand hole gaskits renewed. Hydrostatic pressure of 225 lbs. applied and boilers found tight. All 4 " tubes rerolled. Brickwork, P & S boilers, floors part renewed, sidewalls repaired as found necessary.

Electrical:- The electrical installation examined under working conditions and found satisfactory.

Generators, cables and fittings on the main switchboard and distribution boxes examined.

Insulation tests on all circuits November 1948 and found all to comply to Rule requirements. Minor repairs effected.

In my opinion, the electrical installation is such as could be accepted by the Committee for Classification.

No. 1 Damage stated to have been caused by the vessel grounding or striking submerged object while on a voyage from Dakar to Casa Blaco in ballast October 1st, 1948.

S.S.
"HADIOTIS"

For further particulars please see vessels log, books and copy of special damage report attached

Damage repairs:-

Intermediate line shaft. Three (3) line shaft couplings one of which was the tail shaft coupling disconnected, coupling checked for alignment and line shaft bearings realigned, couplings reconnected and hardened up.

Sea inlet valves opened and examined, sea strainer plates removed.

Sea chests cleaned and coated, strainer plates replaced in good order.

Main injection sea valve found valve seat slack, and valve disc locking nut badly worn.

Valve removed to shop, bronze valve seat renewed, valve disc in way of locking nut built up by welding rethreaded and locking nut renewed, valve tested and replaced on vessel in good condition.

