

No. 109861

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

24 APR 1952

Port of

NEWCASTLE-ON-TYNE

Date of writing Report

in Book. Survey held at

When handed in at Local Office

26 MAR 1952

to

27. 11. 51. Last Survey 7-3. 24. 1952

(No. of Visits 24)

747 on the Machinery of the Wood, Iron or Steel

55. "BORGFRED"

age Gross 1802

Net 1500.

Tonnage 330 MN.

Power 2 WTB.

(SPE).

Donkey Boilers

Main Pressure 250 LB.

Main Boilers 220 LB.

Donkey Boilers

Vessel built at San Francisco, Cal.

Engines made at Alameda, Cal.

Boilers, when made (Main) 1948.

Owners Skib A/S Borgholm.

Managers G. Gabrielsen.

If Surveyed Afloat or in Dry Dock

(State name of Dock)

Tyne Dock Engineering Co.

BS.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER

X for Special Survey.

Date of last Survey and of Periodical Surveys.

Years assigned now expired.

Machinery and Boiler Surveys (including date of N.B., if any)

LMC 4.48.

BS. 3.51.

CL 9.51.

SS. Std.-4.48.

Cargo butter not fitted.

WTB

SEE SPL. NOTE S.R.L (MASHIN)

Particulars of Examination and Repairs (if any) TS: Comp. of LMC. MS.: O.F. Conversion: S.R.L.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the

of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on

nt of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides

detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and

ts of any letters respecting this case

cases where the Surveyor has not made a special damage report he is required to state whether he offered his

services for this purpose, and why they were declined

a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey "

What parts of the Boilers could not be thus thoroughly examined?

at, state for what reasons

at special means, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

latest date of internal examination of each boiler

STARBD 17.2.52. PORT 20.2.52

Present condition of funnel(s)

To what pressure were they afterwards adjusted under steam?

Efficient

MAIN. 250 LB/D

SPT. 220 LB/D

✓

the Surveyor examine the Safety Valves of the Main Boilers?

Yes

To what pressure were they afterwards adjusted under steam?

Yes

and of the Donkey Boilers?

✓

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes

, and of the Donkey Boilers?

✓

the Surveyor examine the drain plugs of the Main Boilers?

Yes

, and of the Donkey Boilers?

✓

the Surveyor examine all the mountings of the Main Boilers?

Yes

Has it a continuous liner?

Yes

Is an approved oil retaining appliance fitted at the after end?

No

If so, state reasons

✓

Has the shaft now fitted been previously used?

✓

Has it a continuous liner?

✓

State date of examination of Screw Shaft

1. 2. 52.

State the wear down in the

approved oil retaining appliance fitted at the after end?

Close fit.

Is electric light and/or power fitted?

Yes

If so, did the Surveyor examine the generators, motors, switchgear cables and fuses?

Yes

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Yes

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Auxiliary machinery should be referred to by position in Machinery Space.

Complete

The Survey is not complete, state what arrangements have been made for its completion and what remains to be done

not done: TS: Completion of LMC. MS.: Vessel placed in dry dock. Examined and found or placed in order the following

machinery items:- Propeller, tailshaft (drawn in) stern bush, sea connections (opened out) and outside

fastenings: main engine cylinders, pistons, slide valves and chests; HP top and bottom end bearings,

dependent pumps, pumping arrangements (tested), main and auxiliary condensers (tested) windlasses

and the electrical installation. The main steam pipes examined and hydraulically tested as per Rules.

BS: Main boilers examined throughout with superheater, mountings, manholes doors

and fastenings and found or placed in safe working condition. Boilers subsequently examined under

beam and safety valves adjusted to pressures stated above.

O.F. Conversion: The vessel has been fitted for oil fuel burning at the time in accordance

with the approved Plans and Rule Requirements. The suction and pressure lines tested as per Rules.

the installation and the deck control gear in connection with the O.F. and Steam Smothering installations

examined and tested under working conditions and all found satisfactory. Particulars of the installation

are as follows: - A secondhand 2nd hand "Babcock &amp; Wilcox" unit comprising 2 oil heaters, suction and

general Observations, Opinion, and Recommendation: - The machinery of the vessel, see continuation sheet

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and

also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &amp;c.; thus, for example, BS 9.11, B&amp;MS 9.11, XLMC 9.11 or

XLMC 140 lb. FD, &amp;c.)

CS 3.34

The vessel is in efficient condition and eligible in our opinion to remain as clared with fresh

records of LMC. MS. 10.51: BS. 3.52: TS (CL) 2.52 and notation "Fitted for oil fuel 3.52, FP. above 150°F"

subject to the L.P. cylinder repair being examined before the end of March 1953 and the steering gear

main shaft and bush being specially examined and dealt with before the end of March 1952.

See Sbm 8583

T.S. 3.0.0.

O.F. conversion 24.0.0.0.

ELECTRICAL 55 FEE 10.0.0.

Travelling expenses (if chargeable) £ 3.0.0.

New General set. £ 3.0.0.

Special date fee. £ 3.0.0.

Committee's Minute

Assigned

Fees applied for

23 APR 1952

Received by me,


19

3.3.0. TUES. 27 MAY 1952

D. G. Taylor, T. Morris, J. M. Wright

Engineer Surveyor to Lloyd's Register of Shipping.

Is a certificate required? If so, to be sent to



009848-009859-010213

SHEET (1)

## SS. "BORGFRED"

pressure filters. Heaters & pressure filters hydraulically tested to 500 lb/I.D. DAT. Whoyds 28.12.51.  
Suction filters Whoyds Test 300 lb. 29.10.43. Lighting up set and hand pump Whoyds 2.1.43.  
2 bars pressure pumps Nos. 165829-30. 19.43. New furnace fronts and burners supplied by  
the Associated British Combustion Ltd. Oil Fuel Transfer Pump. Weir No. 260218 - Size 4x3 $\frac{1}{2}$ x9".  
"White Fox" pneumocator system of sounding fitted to the port & starboard settling tanks.

The Unit Babcock & Wilcox stated as originally examined and found in good order.  
See Glasgow Rpt. No. 76834. The L.P. cylinder repair examined and found to remain efficient. A 5 $\frac{1}{2}$  dia.  
hole now drilled at the end of the crack in both top steam exhaust port locks.

It is recommended that these repairs be examined before the end of March 1953 - repair  
considered efficient mean time. Lt. 4 forwarded to Owners. Copy attached herewith.

Steering Gear. See Cardiff Report Nos 57475 and 57505. The Owners' Superintendent stated  
that as the steering gear had been opened out and examined at Cardiff he would request  
that this item be accepted (for the first record of MS 10,51 as previously recommended).

See Falmouth Report 8. No. 11616

The steering gear pinion shaft and fittings  
examined and the pinion shaft bush found to be worn. It was recommended that  
the bush be renewed. These repairs were put in hand too late to be carried out before  
the vessel sailed for Copenhagen and Oscarshamn. The Owners' Superintendent  
stated that these repairs would be carried out at Oscarshamn, time permitting, or  
on the return of the vessel to the UK in about 3 weeks time.

It is recommended that the steering gear pinion shaft and bush be specially  
examined and dealt with before the end of March 1952. Steering gear tried under  
working conditions and considered efficient mean time.

Lt. 4 forwarded to Owners + Cert B1 placed aboard vessel. Copy attached herewith.

Repairs: - Bottom half of stern bush renewed. (WD found  $\frac{1}{4}$ ). Sea connections overhauled.

Main engine: M.P. valve chest rebedded and valve rings renewed. H.P. piston ring renewed. L.P. piston rings  
and springs renewed. HP & LP crosshead pins machined true and bushes adjusted.

Auxiliaries: Independent circulating pump: impeller shaft, found worn, renewed. Spare shaft  
also made and placed on board. Auxiliary condenser circulating pump: Water end liners renewed,  
ford bucket rod renewed, piston rings renewed. Tank and bilge valves, bilge injection valve  
overhauled. All independent pumps and dynamo engines overhauled, minor repairs effected.

Steering gear: Telemotor system renewed throughout, pipes, tanks transmitting and  
receiving cylinders renewed and all, on completion, satisfactorily tested by Hens Donkin & Co.

Windlass: main and top and bottom end bearings renewed

B5: 15 tubes renewed in the starboard boiler; 16 tubes renewed in the port boiler - tubes found  
to be stopped. Boilers cleaned by chemical process. On completion of repairs boilers hydraulically  
tested. All mountings overhauled. Existing F.D. fans - 2 in each boiler, dispensed with and a  
2nd hand reconditioned steam driven Howden F.D. fan complete with <sup>new</sup> air curing to boilers  
installed at their time. All water gauge cocks renewed on boilers.

A 2nd hand reconditioned diesel generating set has been installed at this time in the port  
timber deck: O.F. steel supply tank for the tank fitted, examined and found satisfactory.

This set has been installed for port use. (Newcastle Rpt 10. attached herewith No. C.37783.)  
A new sea suction valve fitted at port side of the engine room for the set and a new overboard  
discharge valve for cooling water service now fitted. A new overboard discharge valve fitted on  
the starboard side of the stokehold for O.F. transfer pump at this time.

A number of other minor repairs effected to the machinery and on completion the main  
and auxiliary machinery tried under working conditions and found satisfactory.

(SEE CONTINUATION SHEET NO 2.).

Rpt. 9a.

Port of NEWCASTLE-ON-TYNE:

Continuation of Report No. 109361 dated 5th March, 1952

on the

SHEET NO. 2.

S.S. "BORGFRED"

SURVEY OF ELECTRICAL INSTALLATION.

No in Reg. Bk 35947 NAME OF VESSEL -

Capacity of Installation K.W Generators:- 2- 25Kw. 120volts. 1-15kw. 110volts (Diesel driven generator added, for use in port)

Nature of Survey Special Survey.

FIRST SURVEY 28<sup>th</sup> January

LAST SURVEY

5<sup>th</sup> March,

No of Visits 4

Where Surveyed

South Shields

No. OF VISITS

four

A Special Survey of the electrical equipment was carried out. Generators cables, fittings, and main Switchboard examined.

The following repairs and modifications were carried out at this time:- Additional generator set fitted in compartment at top of engine room on port side, "Mawdley" generator No 10052307. 15kw. 110volts 130 amps, 1100 R.P.M. driven by "Lister" diesel engine No 60/14877.

Generator connected to panel comprising D.P. Switch and fuses, Voltmeter, Ammeter, and Field Regulator, mounted in generator compartment. Panel connected to main switchboard through D.P. change-over switch, additional Voltmeter and Ammeter fitted on main Switchboard. Cables and control gear in accordance with rule requirements.

Accommodation, Fore, Aft, and Bridge, partly repaired, alternative circuit wired for navigation lights. Motors overhauled as required, all faults on circuits and fittings rectified.

On completion of repairs installation seen under working conditions generators tested for compounding and governing, steam driven sets tried for parallel operation, circuit breaker trips tried, all circuits megger tested, and all found to be in order.

Certificate of 15kw generator set attached (No C 37783. Newcastle).

J. C. Wright  
SURVEYOR TO LLOYD'S REGISTER  
NEWCASTLE-ON-TYNE.

New M.N. = 234.

Particulars of Machinery obtained for ship's log book.

Total I.H.P. 1300. at 80 R.P.M.

Heating surface per b.t.u. = 2400 ft.

Superheater surface per b.t.u. = 41 ft.

∴ Total H.S. = 4882

D. W. May Jr.

SURVEYOR TO LLOYD'S REGISTER  
NEWCASTLE-ON-TYNE.