



The safety valves adjusted under steam and accumulation test carried out to the above  
It was recommended that the Water Gauge terminal valves be changed for cocks at the ne  
survey.

Selected steam and feed water pipes also superheater coils and headers removed and tes  
hydraulic pressure to 2 times W.P. and found sound and tight.

Discharge port of ash shoot under water line has now been fitted with delivery valve.

Repairs due to wear and tear:-

H.P. Turbine, all labyrinth rings renewed.

Boiler, all bottom main hole flanges built up by E.W. to suit.

Several superheater coil caps rewelded.

Other minor repairs effected.

Interim Certificate issued copy attached.



© 2021

Lloyd's Register  
Foundation