

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port

KIEL
12th January, 1951

This is to Certify that

J. DORRILL & A. HOLTZ (on behalf of the Owners)

the undersigned Surveyor to this Society did at the request of

Messrs. The United Baltic Corporation, Ltd. Kiel-Holtenau, on behalf of Messrs. Bellatty, Hankey & Co. Ltd., Hamburg, and with the consent of the Owners, attend on board the M.V. "OTIS", Official No. 6117, of Rotterdam, as she lay in dry dock and afloat at Howaldtswerke, Kiel, on 14th November, 1950, and subsequently, without prejudice to now admitting liability for damage stated to have been sustained by the vessel's main engine.

It was ascertained on board that the vessel was to be lengthened by approx. 30 feet, and that the existing main propulsion machinery was to be removed and replaced by a new engine of higher power.

After the old engine had been removed, it was recommended that it be partly opened out for an initial examination for condition.

Nos. 1 & 2 cylinder covers removed, pistons drawn and crankshaft bearings exposed. Attached pump opened out, and all examined with the following results:

1. Nos. 1 & 2 cylinder liners, covers and pistons - worn but no damage.
2. Nos. 1 & 2 bottom end bearings - white metal loose and cracked.
3. Nos. 1 & 2 top end bearings and pinions - worn but no damage.
4. M.V. pumps - castings generally wasted.
5. Crankshaft - slightly pitted at No. 2 crankpin.
6. Valve operating gear (examined in place and found in order).

Since the Owners' representatives were unable to state whether the engine would be subsequently placed in service, no recommendations were made and no repairs effected.

In my opinion, the defects under items Nos. 1, 3 & 4 are due to wear and tear, while Nos. 2 & 5 are attributed to mal-adjustment and contaminated lubricating oil, respectively.

From the condition of the crankshaft as far as now seen, immediate repairs are not considered necessary, but it was indicated by the Owners' representative that to comply with a previous condition of classification, viz. the crankshaft to be specially examined by April 1st, would necessitate the opening out of the crankshaft and possibly its removal from the ship for repairs and that this work should, in the opinion of the Owners' representative, be the subject of a claim upon the Underwriters.

S.P.T.O.

Upon the terms of the Rules and Regulations of the Society, which provide that:—
of the Society use their best endeavours to ensure that the functions of the Society are properly
od that neither the Society nor any Member of any of its Committees is under any circumstances
for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
er publication of the Society, or for any error of judgment, default or negligence of any of
reof, or the Surveyors or other Officers or Agents of the Society."

N.M.V. "OTIS"RECOMMENDED:Page No. 4.) (ctd.)

Ship's side sheathing, one table, shelf, electric wiring and heater steam pipes in Officers' mess room in way of repair

Rudder stock twisted to port about 15 degrees and damaged beyond repair.

to be removed for access and to be refitted with part new material.

Steering gear, crosshead, hand steering gear, etc. to be disconnected and to be removed for access and to be refitted. Damaged rudder stock to be removed and a new forged stock to be supplied and refitted 175 mm dia. with 6 new coupling bolts 44 mm dia. Rudder and rudder post to be removed and refitted.

The foregoing recommendations were made with a view to placing the vessel in the same satisfactory condition as she was before the alleged casualty, and the repairs were satisfactorily carried out by Messrs. Baumitwerke, Viersen, between 26th November, 1950, and 17th December, 1950, concurrently with the lengthening of the vessel, for which purpose she was dry docked on 18th November, 1950, and undocked on 17th December, 1950.

The estimated cost of repairs now effected of 6.600,-DM including docking, including staging, cleaning and painting, hose testing of shell plating, is, in our opinion, fair and reasonable.

J. Bowman & A. H. Gray
Surveyors to Lloyd's Register of Shipping.

Fee £ 47. 5. 0
Expenses £ 0. 0. 0

A/c rendered from
London 28/2/51

20 SET 1951

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

During the survey, damage alleged to have been caused by the following casualties was dealt with:

- 1.) As a result of heavy weather whilst on passage from Dakar to Hamburg from 26th June to 2nd July, 1950;
- 2.) By collision with the S.S. "ALGERIA" at Dunkirk on 3rd November, 1950;
- 3.) by grounding at Dieppe while discharging cargo on 9th, 10th and 11th November, 1950;
- 4.) by contact with quay wall and lock gate whilst leaving Dieppe on passage to Kiel on 11th November, 1950.

See log book for further details.

FOUND:

Damage No. 1.)

Lagging in way of oil tank heating steam pipes on port and starboard sides of main deck, torn and part missing.

RECOMMENDED:

Approx. 190' of 3" steam pipe to be thoroughly cleaned and relagged as originally. Steam pipe casing and supports to be removed for access as required and subsequently to be refit.



T his is to Certify that

Damage No. 2.)

Hullwork plate No. 2 (numbered from f'le bhd., set in.

To be faired in place.

1. Starboard stay and bracket bent. 1 side stay and bracket bent. 2 sides of bow davits bent and fittings loose.

To be scraped and repainted.

2.

Main sheer strake plates Nos. 2 & 3 (numbered from fwd.) slightly scored.

To be scraped and repainted.

3. Main sheer strake plate No. 4 (numbered from aft) slightly scored.

To be scraped and repainted.

4. Port aux. engine (4 cylinder Lister)

Engines cylinders opened out, pistons removed and liners drawn.

5. Port aux. engine (4 cylinder Lister)

Pistons broken and cylinder jackets found fouled by mud, and Nos. 3 & 4 pistons found to have been oversizeated, scored and rings broken.

To be cleaned and part renewed (7' 1" fwd. end. of 4" stroke).

6. Sea valves found partly choked.

To be cleaned and repacked.

7. Damage No. 4.)

Shell plates

Portside: numbered from fwd.)

No. 2 sharply set in.

To be faired in place and subsequently to be T.W. welding to be chipped and dressed afterwards.

8. First stroke below poop sheer strake

No. 1 & 2 (numbered from aft) set in way of gun mount.

To be released and faired in place.

9. First stroke below poop sheer strake

No. 4 (numbered from aft, lower)

landing set in, in way of two plates.

To be released and faired in place.

10. Frames Nos. 3 & 4 (numbered from aft)

set in.

To be released and faired in place.

11. Damage to hull

12. Damage to hull

13. Damage to hull

14. Damage to hull

15. Damage to hull

16. Damage to hull

17. Damage to hull

18. Damage to hull

19. Damage to hull

20. Damage to hull

21. Damage to hull

22. Damage to hull

23. Damage to hull

24. Damage to hull

25. Damage to hull

26. Damage to hull

27. Damage to hull

28. Damage to hull

29. Damage to hull

30. Damage to hull

31. Damage to hull

32. Damage to hull

33. Damage to hull

34. Damage to hull

35. Damage to hull

36. Damage to hull

37. Damage to hull

38. Damage to hull

39. Damage to hull

40. Damage to hull

41. Damage to hull

42. Damage to hull

43. Damage to hull

44. Damage to hull

45. Damage to hull

46. Damage to hull

47. Damage to hull

48. Damage to hull

49. Damage to hull

50. Damage to hull

51. Damage to hull

52. Damage to hull

53. Damage to hull

54. Damage to hull

55. Damage to hull

56. Damage to hull

57. Damage to hull

58. Damage to hull

59. Damage to hull

60. Damage to hull

61. Damage to hull

62. Damage to hull

63. Damage to hull

64. Damage to hull

65. Damage to hull

66. Damage to hull

67. Damage to hull

68. Damage to hull

69. Damage to hull

70. Damage to hull

71. Damage to hull

72. Damage to hull

73. Damage to hull

74. Damage to hull

75. Damage to hull

76. Damage to hull

77. Damage to hull

78. Damage to hull

79. Damage to hull

80. Damage to hull

81. Damage to hull

82. Damage to hull

83. Damage to hull

84. Damage to hull

85. Damage to hull

86. Damage to hull

87. Damage to hull

88. Damage to hull

89. Damage to hull

90. Damage to hull

91. Damage to hull

92. Damage to hull

93. Damage to hull

94. Damage to hull

95. Damage to hull

96. Damage to hull

97. Damage to hull

98. Damage to hull

99. Damage to hull

100. Damage to hull

101. Damage to hull

102. Damage to hull

103. Damage to hull

104. Damage to hull

105. Damage to hull

106. Damage to hull

107. Damage to hull

108. Damage to hull

109. Damage to hull

110. Damage to hull

111. Damage to hull

112. Damage to hull

113. Damage to hull

114. Damage to hull

115. Damage to hull

116. Damage to hull

117. Damage to hull

118. Damage to hull

119. Damage to hull

120. Damage to hull

121. Damage to hull