

REPORT ON STEAM RECIPROCATING ENGINE MACHINERY.

Received at London Office 18 DEC 1942

Date of writing Report Aug. 17th 1942 When handed in at Local Office Aug. 17th 1942 Port of MONTREAL, QUE.

No. in Survey held at MONTREAL, QUE. Date, First Survey 28th May, 1942 Last Survey 7th July 1942

Reg. Book. on the SS "FORT SOURIS" (Number of Visits 29) Tons {Gross 7133.58
Net 4243.53.

Built at VANCOUVER, B.C. By whom built WEST COAST SHIPBUILDERS LIMITED Yard No. 108 When built 1942

Engines made at LACHINE, P.Q. By whom made DOMINION ENGINEERING WORKS LTD Engine No. 39 When made 1942

Boilers made at By whom made Boiler No. When made

Registered Horse Power Owners Port belonging to Is Electric Light fitted Yes

Nom. Horse Power as per Rule 504 505 Is Refrigerating Machinery fitted for cargo purposes. No

Trade for which Vessel is intended

ENGINES, &c.—Description of Engines Triple Expansion - Revs. per minute 76

Dia of Cylinders 24 1/2 x 37 x 70 Length of Stroke 48 No. of Cylinders 3 No. of Cranks 3

Crank shaft, dia. of journals 14.07 14.00 Mid. length breadth - Thickness parallel to axis 9" & 9 1/2" L.P.

as fitted 14 1/4" Crank pin dia. 14 1/4" Crank webs shrunk Thickness around eye-hole 7.125

Intermediate Shafts, diameter 13.2 13.72 Mid. length thickness - Thrust shaft, diameter at collars 13.82 14.25

as fitted 13.5 as fitted 14.25

Tube Shafts, diameter - Screw Shaft, diameter 14.875 14.86 Is the tube shaft fitted with a continuous liner? Yes

as fitted - as fitted 15.25 as fitted 15.65"

Bronze Liners, thickness in way of bushes .75" Thickness between bushes .68" Is the after end of the liner made watertight in the propeller boss Yes Solid -

If the liner is in more than one length are the junctions made by fusion through the whole thickness of the liner tight fit -

If the liner does not fit tightly at the part between the bearings in the stern tube, is the space charged with a plastic material insoluble in water and non-corrosive Yes

If two liners are fitted, is the shaft lapped or protected between the liners - Is an approved Oil Gland or other appliance fitted at the after end of the tube shaft No If so, state type -

Length of Bearing in Stern Bush next to and supporting propeller 61"

Propeller, dia. 18'-6" Pitch 16'-0" No. of Blades 4 Material Bronze whether Moveable Solid Total Developed Surface 117 sq. ft.

Feed Pumps worked from the Main Engines, No. None Diameter - Stroke - Can one be overhauled while the other is at work -

Bilge Pumps worked from the Main Engines, No. Two Diameter 4 1/2" Stroke 26" Can one be overhauled while the other is at work Yes

Feed {No. and size Pumps connected to the {No. and size
Pumps {How driven Main Bilge Line {How driven

Ballast Pumps, No. and size Lubricating Oil Pumps, including Spare Pump, No. and size

Are two independent means arranged for circulating water through the Oil Cooler Yes Suctions, connected to both Main Bilge Pumps and Auxiliary Bilge Pumps;—In Engine and Boiler Room Yes

In Pump Room Yes In Holds, &c. Yes

Main Water Circulating Pump Direct Bilge Suctions, No. and size Independent Power Pump Direct Suctions to the Engine Room Bilges,

No. and size Are all the Bilge Suction Pipes in holds and tunnel well fitted with strum-boxes

Are the Bilge Suctions in the Machinery Space led from easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges Yes

Are all Sea Connections fitted direct on the skin of the ship Are they fitted with Valves or Cocks

Are they fixed sufficiently high on the ship's side to be seen without lifting the stokehold plates Are the Overboard Discharges above or below the deep water line

Are they each fitted with a Discharge Valve always accessible on the plating of the vessel Are the Blow Off Cocks fitted with a spigot and brass covering plate

What Pipes pass through the bunkers How are they protected

What pipes pass through the deep tanks Have they been tested as per Rule

Are all Pipes, Cocks, Valves, and Pumps in connection with the machinery and all boiler mountings accessible at all times Yes

Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo or machinery spaces, or from one compartment to another Is the Shaft Tunnel watertight Is it fitted with a watertight door worked from

MAIN BOILERS, &c.—(Letter for record S) Total Heating Surface of Boilers 7140 square feet -

Which Boilers are fitted with Forced Draft All three - Which Boilers are fitted with Superheaters All three

No. and Description of Boilers 3 Single Ended Multitubular Working Pressure 220 lbs. per square inch -

IS A REPORT ON MAIN BOILERS NOW FORWARDED? Yes

IS A DONKEY BOILER FITTED? No If so, is a report now forwarded? -

Can the donkey boiler be used for domestic purposes only -

PLANS. Are approved plans forwarded herewith for Shafting Yes Main Boilers Yes Auxiliary Boilers Yes Donkey Boilers Yes

(If not state date of approval)

Superheaters General Pumping Arrangements Oil fuel Burning Piping Arrangements Yes

SPARE GEAR.

Has the spare gear required by the Rules been supplied YesState the principal additional spare gear supplied Yes

The foregoing is a correct description

Dominion Engineering Works Ltd Manufacturer.

per A.L. Van Patten



© 2021

Lloyd's Register
Foundation

009486-009993-0009

P11

ST

GLA

BO

SIL

S

SID

S

JP

S

JP

S

TR

S

TR

S

CO

RI

OI

T

I

F

S

C

F

S

I

F

S

C

F

S

I

F

S

C

F

S

I

F

S

C

F

S

I

F

S

C

28,29,30th May, 1942, 1,2,3,4,5,6,8,10,11,12,13,15,17,18,19,22,23,24,25,26,27,29,30th

During progress of work in shops - - June, 1942, 2,3,7th July, 1942

Dates of Survey while building

During erection on board vessel - -

Total No. of visits

Dates of Examination of principal parts—Cylinders 21.4.42, 2.6.42, 24.6.42 Slides 21.4.42, 2.6.42, 24.6.42 Covers 21.4.42, 2.6.42, 24.6.42

Pistons 21.4.42, 2.6.42, 24.6.42 Piston Rods 7.7.42 Connecting rods 7.7.42

Crank shaft 7.7.42 Thrust shaft Intermediate shafts

Tube shaft Screw shaft Propeller

Stern tube Engine and boiler seatings Engines holding down bolts

Completion of fitting sea connections

Completion of pumping arrangements Boilers fixed Engines tried under steam

Main boiler safety valves adjusted Thickness of adjusting washers

Crank shaft material O H Steel Identification Mark 3874 H.S. Thrust shaft material O H Steel Identification Mark 6959 A.S. 7.7.42 25.5.42

Intermediate shafts, material Identification Marks Tube shaft, material Identification Mark

Screw shaft, material Identification Mark Steam Pipes, material Test pressure Date of Test

Is an installation fitted for burning oil fuel No Is the flash point of the oil to be used over 150°F.

Have the requirements of the Rules for the use of oil as fuel been complied with -0-

Is the vessel (not being an oil tanker) fitted for carrying oil as cargo If so, have the requirements of the Rules been complied with

If the notation for Ice Strengthening is desired, state whether the requirements in this respect have been complied with

Is this machinery duplicate of a previous case Yes If so, state name of vessel S/S "FORT TADOUSSAC" & S/S "FORT CHAMBLY"

General Remarks (State quality of workmanship, opinions as to class, &c. This ENGINE has been constructed under Special Survey

in accordance with the Rules and Approved Plans. The materials and workmanship are good. The cylinders were tested

hydrostatically to 330, 110 and 30 lbs. pressure per square inch respectively, and found tight under those pressures.

This ENGINE has now been shipped to WEST COAST SHIPBUILDERS LIMITED, VANCOUVER, B.C., for installation and official

trials. It is recommended for the favourable consideration of the Committee that the record of * L.M.C. (with date)

be made in the Register Book in the case of this Vessel, subject to satisfactory installation and sea trials.

The amount of Entry Fee ... £/ \$30.00 : When applied for, 30.10.19 42 VCR.
Special ... £/ \$267.00 :
Donkey Boiler Fee ... £ : :
Travelling Expenses (if any) £ : :
When received, RB

H. J. Saunders
Engineer Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUE. 12 JAN 1943

Assigned Sec Vcr. 76 5829



© 2021

Lloyd's Register Foundation

is a report also sent on the hull of the ship

[2M-7-41—Copyright Ink.] (Printed in U. S. A.)