

No. 35369^b

PORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

13 OCT 1952

of writing Report. 18-9-1952 When handed in at Local Office.

to Port of Rotterdam

Survey held at Rotterdam - Yselmonde Date. First Survey 20-5-52 Last Survey 25-9-1952
P329 (No. of Visits 25)

on the Machinery of the Wood, Iron or Steel Arm. Trawler "MERKURY"

GROSS 352
Net 147
Tons 96 MM
in Boilers 4
Donkey Boilers ✓
Pressure -
in Boilers 2000
Key Boilers

Vessel built at Finsbury
Engines made at Hull

By whom Cook, Willm & Gennell Rd.
By whom C.J. Holmes 800 Rd

Year. Month.
When 1926 ✓
When 1926

Boilers, when made (Main)
Owners Polish Government

(Donkey)

Owners' Address

(if not already recorded in Appendix to Register Book.)

Managers, Palmar "Pradnicki's Płowno Port Gdynia Voyage ✓
Dalekomożność Sp. z o.o. 6

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

In City dock - afloat

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. X for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)
Stm. Trawler	✓	
Gdy 4.50		
SS ANT - 4,46		

Report No. Port

Details of Examination and Repairs (if any) Re-classification - TS.
All Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides listed in the body of the report, should be briefly summarised at the end of the report. State also the dates and any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Donkey " " " " What parts of the Boilers could not be thus thoroughly examined? All parts examined

for what reasons? Official means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Test date of internal examination of each boiler 13-6-52 Present condition of funnel(s) good.

Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? 200 lbs

Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? Yes , and of the Donkey Boilers?

Screw shaft now been drawn and examined? Yes Has it a continuous liner? Yes Is an approved oil retaining appliance fitted at the after end? No

If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

It now been changed? No State date of examination of Screw Shaft 7-7-52 State the wear down in the

Approved oil retaining appliance fitted at the after end? 1.8 m/m Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? Yes

bush. Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Vessel placed in drydock, screwshaft drawn. Found top of cone rust pitted. Cone

lined up to 202 m/m at top, shaft re-examined and found good. New 4 bladed cast

propeller fitted. Sternbush, sea connections, their fastenings etc, found good.

Main engine removed to shop for general overhaul & afterwards refitted. Chocks & holding-

on bolts removed, alignment of shafting checked & found good. Main engine cylinders,

stays, rods, slide valves & valve motion gear etc. Crank & thrustshaft etc. Attached

pumps, main circulating pump, engine and general service pumps etc. Condenser etc

and tested. Valves, cocks, pipes & strainers of the pumping arrangements etc

The main boiler and internally & externally together with manholes, doors and

mountings and safety valves adjusted under steam to the above stated pressure.

Main & auxiliary steam pipes removed, etc internally & hydraulically tested.

The electric equipment and tested as required by the Rules.

Auxiliary machinery tried under working conditions & found in good working & manoeuvring order.

General Observations, Opinion, and Recommendation:

Please see continuation sheet.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and

also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9/11, B&MS 9/11, LLMC 9/11 or

LLMC 140 lb., FD, &c.)

CS 3,34

The machinery of this vessel is in good condition and eligible in our opinion

to be re-classed with fresh record of LLMC 8/52 and screwshaft seen

8/52 C.L.

Fee (per Section 23) £ 100/- 15/- Std. £ 260/-

Repair Fee (if any) (per Section 23) £ 250/-

Engineering expenses (if chargeable) £ 80/-

Committee's Minute TUES. 28 OCT 1952

signed

Red X

TUES. 28 OCT 1952

5 7-52 CERTIFICATE WRITTEN.

Red X

Red X</p

Rpt. 9a.

Port of

Rotterdam

Continuation of Report No. 35369^b dated 10-9-52

on the

Steam Trawler "Mercury".

Repairs due to wear & tear: Main engine crankshaft renewed (journals & crankpins loose). Main bearings & bottom ends remetalled. Collar faces of thrust shaft skimmed up, horseshoes remetalled. 4 longitudinal stays in steam space of boiler renewed (excessively reduced in diameter). All plain & stay tubes renewed. A number of screw-stays & griddle stays renewed. Centre furnace jacked fair. Main auxiliary feedwater chest, blow down valve chest renewed. Boiler hydraulically tested after repairs and found good.

J. Baart Esq. in Rotterdam