

DISCLOSED  
Report of Survey for Repairs, &c., of Engines and Boilers.DISCLOSED  
BAY No. 11804

No. 11804

(Received at London Office)

15 JUL 1941

Date of writing Report 17/5/41. When handed in at Local Office 17th May 41. Port of Kobe.  
No. in Reg. Book. Survey held at Kobe. Date, First Survey 2/5/41 Last Survey 14/5/1941.  
(No. of Visits Two.)  
80541 on the Machinery of the ~~Kobe~~ Steel M.S. "NOTO MARU"  
Tonnage { Gross 7191 Vessel built at Nagasaki. By whom Mitsubishi Jukogyo K.K. When 1934 10mo.  
Net 4311 Engines made at Nagasaki. By whom Mitsubishi Jukogyo K.K. When 1934.  
Nominal Horse Power 1851 NHP Boilers, when made (Main) -- (Donkey) 1934.  
No. of Main Boilers -- Owners Nippon Yusen Kabushiki Kaisha. Owners' Address  
(if not already recorded in Appendix to Register Book.)  
No. of Donkey Boilers 1 Managers Port Tokyo. Voyage  
Steam Pressure in Main Boilers -- If Surveyed Afloat or in Dry Dock Afloat.  
(State name of Dock.)  
in Donkey Boilers 100 lbs. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report No. 7035 Port Tka.

## Particulars of Examination and Repairs (if any) REPAIR.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

If this was not done, state for what reasons?

Not submitted for survey at this time.

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler

Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers?

, and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers?

, and of the Donkey Boilers?

Has screw shaft now been drawn and examined?

Is it fitted with continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used?

Has it a continuous liner?

Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

State date of examination of Screw Shaft

State the distance between lignum vitae or ~~wooden~~ of stern bush and top of after bearing of screw shaft

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and power fitted? Yes.

If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Yes, Generally.

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

Yes.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

Complete.

NOW DONE:- Main Engine, No. 6 piston leg renewed on account of crack on one of the vertical lub.

## Marks on new leg:-

: A.S.C. 1202 :  
: LLOYD'S No. 2282. :  
: W.T.P. 12 KG. :  
: 2 - 4 - 41. :

One spare piston leg placed on board.

## Marks:-

: A.S.C. 1167 :  
: LLOYD'S No. 2276 :  
: W.T.P. 12 KG. :  
: 4 - 3 - 41. :

General Observations, Opinion, and Recommendation. The machinery of this vessel, so far as now

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.S.M.S. 9, 11, & L.M.C. 9, 11, or

\*L.M.C. 140 lb., F.D., &c.)

seen, is in good condition and eligible, in my opinion, to be continued as now classed and machinery record be retained in the Register Book.

Survey Fee (per Section 20) Yen 30:00

Fees applied for 14/5/1941

Special ~~XXXXXX~~ Repair Fee (if any) (per Section 20.) Yen 6:00

Received by me,

Travelling expenses (if chargeable) Yen 6:00

Committee's Minute

FRI. 25 JUL 1941

WED. 27 MAY 1942  
OMIT CLASS  
ON RE-PR

Assigned

As now

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

010004-010011-0171



*Apiston partly renewed.*

It is submitted that  
this vessel is eligible to  
remain as CL488ND.

*BA*

*22/7/41*



© 2021

Lloyd's Register  
Foundation