

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... When handed in at Local Office... Port of...  
 No. in Survey held at... Kobe Date, First Survey... 2nd September Last Survey... 5th September, 1954  
 Reg. Book... M.V. "TOKYO MARU" (No. of Visits... 3)

TONNAGE: — Built at Yokohama By whom Higashi Nippon Jukogyo K.K. When YEAR 1952 MONTH 2mo  
 GROSS 6574 Owners Tokyo Sempaku K.K. Owners' Address —  
 UNDER DK. 5706 Managers — Port belonging to Tokyo  
 NET 3766

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
 Cell DB or DBa feet: uE&B feet: f feet  
 total capacity tons: FPT tons: APT tons: MT feet tons

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 1264 Port

Periodical Surveys, when held, must be reported in detail and periodically in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacements Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified

OIL ENGINES

CONTINUOUS SURVEY.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR Damages stated caused (a) through vessel ranging along side the Pier at R.M.C.(ED.) Shimizu, Japan during typhoon on the 18th August, 1954 and (b) by striking the Pier wall at Kawasaki Harbour, Japan on the 28th August, 1954 and Drydocking.

Now Done:— Vessel placed in drydock, bottom and rudder cleaned, examined and recoated. The decks, casings, hatchways, ventilators and closing appliances, steering gear, windlass & equipment generally examined & found in good & efficient condition.

Damage:— (a) Shell plates numbered from Aft. Portside damage in way of No.3 & 4 hold & Engine Room.

H7, H9, H11, G8, G9, F7, F9 & F11 faired in place.

G7 & G11 cropped, removed, faired, & refitted.

Main frames (F56) cropped, removed, faired, & refitted and (F105) faired in place.

Tween deck beam (F56) cropped, removed, faired, & refitted beam knee removed, faired & refitted. (P.T.O.)

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates (a) (b)	Frames (a) (b)	R. Frames	Floors and Bracket Floors	Beams (a) (b)	Inner Bottom Plates	Dk. Plates	Other Items:—
Renewed...								
CROPPED								
Removed and Faired or Repaired	2	1	1		1			
Faired or Repaired in place	8	4	1					

## PRESENT CONDITION OF THE

Decks	Good	Bulkheads	Not Exd.	Engine Room Skylights	Good	Copper, or Y.M.	
Caulking of Decks	"	Ceiling	"	Coal Bunkers, Openings, Covers, &c.	—	(State if on Felt.)	
Coamings	"	Cement or Asphalt	"	Oil Bunkers	Not Exd.	When fitted Month	Year
Beams & Fastenings	Not Exd.	Rudder	Good	Scuppers	"	Boats	Good
Outside Plating	Good	Steering gear and its connections	"	Cargo Hatchways	Good	Masts, Yards, &c.	"
" " in way of sidelights	Not Exd.	Windlass	"	Hatches	"	Condition, how ascertained, from deck	
Frames	"	Have pumps been examined and found efficient?	Not Exd.	Planking		(State if wedges removed.)	A* (2")
Reverse Frames	"	Have Sluice Valves been examined and found efficient?	Not Exd.	Caulking		Equipment letter	3B 1S
Longitudinals	—	Have Watertight Doors been examined and found efficient?	—	Treenails		Anchors, No. of	3B 1S
Transverses	Not Exd.	Have Ventilators and their Coamings been examined and found efficient?	Yes	Breasthooks & Stemson		Cables (State if now ranged)	Yes
Floors	—	Air and Sounding Pipes	Not Exd.	Transoms, Pointers & Crutches		" length 270 mean diamr.	2"
Keelsons	Not Exd.	Doubling Plates under Sounding Pipes	"	Timbers of Frame at openings		" Rule length 270 size	2"
Stringers	"			" " at other places		Chain Locker	Not Exd.
Inner Bottom Plating	—			Stringers, Clamps & Shelves		Hawsers & Warps	Sufficient
Have the Tanks been examined internally?	No			Salting	State if examined	Standing and Running Rigging	Efficient
Have the Tanks been tested?	No					Sails	—

## General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel, so far as now seen, is in good & efficient condition & is eligible in my opinion to remain as now classed without fresh record of Survey & with fresh record of drydocking 9,54 subject to the stern frame (E.W. 9/53 & 9/54), Nos. 1,2, & 3 keel plates (pitted) from ford and set up bottom shell plating in way of machinery space and No.3 hold (p.s. A7,A8 & C11, ss. A7,A8, B8,B9 & C10) being specially examined at the next drydocking.

Survey Fee (per Section 23)	£ 15,000	Fees applied for,	SEP 11 1954
Special Damage or Repair Fee (if any) (per Sec. 23)	£ 20,000	Received by me,	19
Travelling Expenses (if chargeable)	£		
Special Attend. Fees	£ 8,000		
Second Surveyor's Fee (if any)	£		

Committee's Minute WEDNESDAY 13 OCT 1954

Character Assigned

Q. 54 Kob. subject

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation



