

d by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

EL'S NAME "NICHIEI MARU" REPORT Kob. 322
Kob. No. 378

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine 2 Steam turbines with D.R. gearing to one screwshaft.

HS 18139 sq.ft.

MN 1612

If Boilers fitted with forced draught Yes

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 17. 7. 51 for a service speed of 114 R.P.M.

The main gear wheel teeth were damaged by earthquake during construction and the Surveyor recommended this be re-examined after six months' service. This has been done and all found in order.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

* LMC 12.50,
"Carrying Petroleum in Bulk"
3 WTB 313 lb. (Spt.) F.D.
"Fitted for O.F. 12/50. F.P. above 150°F."



© 2021

20. 8. 51.

Lloyd's Register
Foundation