





MAR 1954

PART MACHINERY OF THE ms. "BENMORE".

been repaired by welding.

The Port aftermost tie-bolt (for no. 8 cylinder) was found broken and has been renewed. For the above repairs it was necessary to remove the after section of the camshaft and to transport it to the workshop.

Repairs examined and upon completion found satisfactory.

Gear wheels for camshaft drive of Starb. Main engine examined and found small indent in one tooth of first intermediate wheel and all teeth of cog-wheel on camshaft more or less indented. It has been recommended that this gearing be specially examined at the Special Survey by the end of August next.-

*Assemit*