

Report of Survey for Repairs, &c., of Engines and Boilers.

23 JUL 1923

(Received at London Office

WED. JUL 25 1923

of writing Report 10 When handed in at Local Office 10 Port of **LIVERPOOL**

Survey held at **Liverpool & Birkenhead** Date, First Survey **5th July** Last Survey **18th July 1923**

30 on the Machinery of the **Wood, Iron or Steel** **4 Mast. s/s "CHLORIS", ex "EIDER"** (No. of Votels **8**)

Gross **1443** Vessel built at **Rendsburg** By whom **Werft. Nobiskrug G.m.b.H.** When **1921**

Net **642** Engines made at **Altona** By whom **Ottensener Mch. G.m.b.H.** When **1921**

4 * Power **111** Boilers, when made (Main) **01. 1921** (Donkey)

Main Boilers **3 nos** Owners **J. & P. Hutchinson & Co.** Port **Glasgow** Voyage

Donkey Boilers Pressure **185** Surveyed Afloat in Dry Dock **Waterloo & Clowes (Dry)**

Donkey Boilers (State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Survey (including date of S.B., if any).

Report No. _____ Port _____

Particulars of Examination and Repairs (if any) **L.M.C.**

Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on damage (the cause of which must be stated) should be separated from repairs due to other causes; and any detailed in the body of the report, should be briefly summarised at the end of the report. State also the initials of any letters respecting this case.

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were refused?

Was a damage report made by anyone else? If so, by whom?

Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? **Yes**

" Donkey " " "

What done, state for what reasons?

Parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Surveyor examine the Safety Valves of the Main Boiler? **Yes** To what pressure were they afterwards adjusted under steam? **185 lb/0"**

Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? **Yes**, and of the Donkey Boiler?

Surveyor examine the drain plugs of the Main Boilers? **None**, and of the Donkey Boiler?

Surveyor examine all the mountings of the Main Boilers? **Yes**, and of the Donkey Boiler?

Shaft now been drawn and examined? **Yes** Is it fitted with continuous liner? **No** Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? **Yes**

Shaft now been changed? **No** If so, state reasons

Shaft now fitted new? Has it a continuous liner Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Clearance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft? **1/16"**

Is not complete state what arrangements have been made for its completion and what remains to be done? **Complete.**

Vessel placed in dry-dock: the propeller, stern-bush, sea-connections, fastenings examined & found or placed in good condition.

Screw-shaft drawn, examined & found in good condition. The cylinders, pistons, piston & slide-valves, crank, thrust and intermediate shafting, crosser, pumps and bilge connections, steering engine and aux. g. machinery examined. Engines generally overhauled and tested; afterwards tried under steam. The Boilers, together with superheaters & mountings, examined throughout, & found in good condition: no sign of strain was observed in furnaces nor in dome flange attachment. ^{see Secretary's letter of 18.6.23.} Safety valves afterwards adjusted under steam. New tank injection valve fitted.

See First Entry Report forwarded herewith.

Observations, Opinion, and Recommendation:— The Machinery of this Vessel is in good condition, and in our opinion eligible to be classed in Lloyd's Register Society's Register Book with records of L.M.C. 7.23, and screw shaft examined (O.G.) 7.23.

Section 28) Application for Repair Fee (if any) £ 20:0:0

Section 28.) Fees applied for 10

Received by me **CW REED and S. Townsend** 23/7/23

Engineer Surveyor to Lloyd's Register of Shipping.

ee's Minute LIVERPOOL 24 JUL 1923

See J.E. report attached

FRI. 12 OCT. 1923

FRI. 14 MAR. 1924

FRI. MAR 27 1924

Lloyd's Register Foundation

Insert Character of Ship and Machinery precisely as in the Register Book. Is a Certificate required? If so, to be sent to...

The vessel was built at Kendsburg
in 1921 & classed with the German Lloyd.

The machinery has been
opened out & examined & is now
satisfactorily reported upon.

If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. LMC 7. 23. 0G.

57.23. 1857b.

J.W.D.
28/7/23
CERTIFICATE WRITTEN 9/8/23

[Faint handwritten notes and bleed-through from the reverse side of the page, including the word 'Holding' and various technical details.]

