

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME "LA PLATA" REPORT Rot. No. 33203

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine 2 Oil Engines 2 S.C.S.A.

10 Cyl. 29 $\frac{1}{8}$ " - 63"

MN 1608

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 7. 7. 50 for a service speed of 115 R.P.M., provided a notice board be fitted at the control station stating that the engine must not be run continuously between 51 and 62 R.P.M.

The Machinery Certificate should be endorsed accordingly and a suitable note placed in the S.R.L.

Similar calculations for the 230 KW generator sets were approved in the Secretary's letter of 11. 7. 49 for a service speed of 425 R.P.M.

The lighting fittings installed in the bridge 'tween deck do not comply fully with the Rule requirements for flame-proof enclosure, and the matter is dealt with in endorsement dated 5. 1. 51.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed LMC 12.50, subject to rubber bushes in cable glands of lighting fittings in bridge 'tween deck to be replaced by lead bushes at first opportunity.

"Carrying petroleum in bulk"

2 WTDB 180 lb.

2 DB 180 lb.

The Rotterdam Surveyors should be informed that the certificates covering the left hand propellers do not appear to have been received and should be forwarded as soon as possible.

5. 3. 51.

© 2021

Lloyd's Register
Foundation

010519-010525-0023