

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 7th June 1950.

When handed in at Local Office 1950.

Port of Bremerhaven

No. in Reg. Book. Survey held at Bremerhaven

Date, First Survey

and Last Survey 3rd June 1950.

(No. of Visits 0.42 (1))

57991-07867 on the Wood/1st/4th/Steel Steam Trawler "EDOUARD ANSELEN"

TONNAGE :-

GROSS 338

UNDER DECK 313

NET 129

Built at Selby

By whom Cochrane & Sons, Ltd.

When 1926

MONTH 6

Owners Soc. Anon. Armement Ostendais

Owners' Address

(If not already recorded in Appendix to Register Book)

Managers

Port belonging to Ostend,

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Kaiser Dry Dock No. 1

Destined Voyage

Cell DBor DBa feet; uE & B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 25445 Port Ant-

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.	Machinery and Boiler Surveys (Including date of N.B., if any).
100 A1 Stm. Trawler/LMC 8.48	
Ost. 3.48 7/49	BS 7.49
Cl 3.48	
Reclassified 8.48	
ss Ost. 8.48 (Dr.)	

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking.

NOW DONE: Vessel placed in dry dock. Bottom and rudder cleaned, examined, and coated.

REPAIRS: Rudder lifted.

Top locking pintle renewed. Bush in order.

2nd and 3rd pintles, bushes renewed.

DAMAGES: (Portside no damage).

Starboardside, First and second below sheer, No. 4 plate waved between frames.

Stringer angle, shell rivets in No. 3 and 4 plates rubbed.

The above damages are considered in category "B". Repairs be made at Owners' convenience.

Propeller wear down, 1.7 mm.

Sea valves, grids removed but valves not opened up.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Bulkheads	—	Engine Room Skylights	good	Copper, or Y.M. (State if on Felt.)	When fitted, Month	Year
Caulking of Decks	good	Ceiling	good	Coal Bunkers, Openings, Covers, &c.	—	Boats	good	
Coamings	good	Cement or Asphalt	good	Oil Bunkers	—	Masts, Yards, &c.	good	
Beams & Fastenings	good	Rudder	good	Scuppers	—	Condition, how ascertained (State if wedges removed)	from deck	
Outside Plating	good	Steering gear and its connections	—	Cargo Hatchways	good	Equipment letter		
" " in way of sidelights	—	Windlass	good	Hatches	good	Anchors, No. of		
Frames	—	Have pumps been examined and found efficient?	no	Planking	—	Cables (State if now ranged)	no	
Reverse Frames	—	Have Sluice Valves been examined and found efficient?	no	Caulking	—	" length mean diam. (on board.)		
Longitudinals	—	Have Watertight Doors been examined and found efficient?	no	Treenails	—	" Rule length size		
Transverses	—	Have Ventilators and their Coamings been examined and found efficient?	yes	Breasthooks & Stemson	—	Chain Locker		
Floors	—	Air and Sounding Pipes	—	Transoms, Pointers & Crutches	—	Hawsers & Warps		
Keelsons	—	Doubling Plates under Sounding Pipes	—	Timbers of Frame at openings	—	Standing and Running Rigging		
Stringers	—			" " at other places	—	Sails		
Inner Bottom Plating	—			Stringers, Clamps & Shelves	—			
Have the Tanks been examined internally?	no			Saiting	—			
Have the Tanks been tested?	no			State if examined.				

General Observations, Opinion as to Class, Recommendation, &c. :-

This vessel

(State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38.")

is eligible in my opinion to remain as classed in the Register Book with fresh record of dry docking.

Survey Fee (per Section 29) £ 4 : 4 : 0 Fees applied for,

Special Damage or Repair Fee (if any) (per Sec. 29) £ :

Travelling Expenses (if chargeable) £ 0 : 10 : 0

Second Surveyor's Fee (if any) £ :

Committee's Minute

Character Assigned

FRI, 30 JUN 1950

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation