

(Received at London Office)

25 OCT 1948

No. 55214

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of HULL  
 No. in Reg. Book. 74877 Survey held at HULL Date, First Survey 6. 10. 48 Last Survey 11. 10. 19 48  
 on the Wood, Iron or Steel s.s. "SHEAF LEAD" (No. of Visits.....2.....)

TONNAGE :- Built at Baltimore, Md. By whom Bathlehem Fairfield Shipyard, Inc. When 1943  
 GROSS 7271 Owners Sheaf Steam Shipping Co., Ltd. Owners' Address Sheaf, York  
 UNDER DK. 6729 Managers W.A. Souter & Co., Ltd. Port belonging to Newcastle  
 NET 4454

Surveyed Afloat or in Dry Dock? Afloat Name of Dock King George Dock Destined Voyage -  
 Cell DBor DBa \_\_\_\_\_ feet; uE & B. \_\_\_\_\_ feet; f \_\_\_\_\_ feet  
 total capacity \_\_\_\_\_ tons. FPT \_\_\_\_\_ tons; APT \_\_\_\_\_ tons; MT \_\_\_\_\_ feet \_\_\_\_\_ tons.

Only alterations in the existing records of tanks should be inserted.  
 N.B.—All alterations in the existing records should be underlined.

Last Report, No. \_\_\_\_\_ Port \_\_\_\_\_

Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
100A1 (Classification contem- plated) 6.47.	L.M.C. 6.47 TSCL 5.47
"Examined 6.47"	
Fitted for oil fuel.	W.T.B.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship and now verified } \_\_\_\_\_ ft. \_\_\_\_\_ ins.

Was a damage report made by anyone else? if so, by whom? \_\_\_\_\_

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion of Classification.  
 (See copy of Newcastle letter dated 1st October, 1949).

NOW DONE:- Watertight door fitted to engine room bulkhead to replace hinged door to tunnel.  
Door tried under working conditions on completion of fitting and found satisfactory.  
The door and control gear comply with the requirements of the Rules.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ... ..								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.) When fitted, Month _____ Year _____
Decks	Celling	Coal Bunkers, Openings, Covers, &c.	Boats
Caulking of Decks	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
Coamings	Rudder	Scuppers	Condition, how ascertained (State if wedges removed.)
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Equipment letter _____
Outside Plating	Windlass	Hatches	Anchors—No. of _____
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	Cables (State if now ranged) _____
Frames	Have Sluice Valves been examined and found efficient?	Caulking	" length _____ mean diamr. _____ (on board.)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" Rule length _____ size _____
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Chain Locker
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	Hawsers & Warps
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Standing and Running Rigging
Keelsons		" " at other places	Sails
Stringers		Stringers, Clamps & Shelves	
Inner Bottom Plating		Salting	
Have the Tanks been examined Internally?		State if examined.	
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."


This vessel is eligible in my opinion to be classed 100A1 with Notation of S.S. Lon. 6.47 as previously recommended.

Survey Fee (per Section 29) _____ £	: :	Fees applied for,
Late attendance fee _____ £	3 : 3	22 OCT 1948
Special Damage or Repair Fee (if any) _____ £	: :	Received by me,
Travelling Expenses (if chargeable) _____ £	: :	19
Second Surveyor's Fee (if any) _____ £	: :	

*L. Tait Williams*

Surveyor to Lloyd's Register of Shipping.

Committee's Minute/ \_\_\_\_\_  
 Character Assigned See minute on  
When for rpt. 115429



Is Certificate required? If so, to be sent to \_\_\_\_\_