

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 2-8-55 When handed in at Local Office 2-8-55 Port of GENOA
 No. in Survey held at GENOA & SPEZIA Date, First Survey 2-7-55 Last Survey 17-7-55
 Reg. Book 51676 on the ~~Wooden~~ Steel M/TANKER "ANTONIO ZOTTI" (No. of Visits 12)

TONNAGE: Built at MONFALCONE By whom CANTIERI RIUNITI DELL'ADRIATICO When LAUNCHED 1944 MONTH
 GROSS 6200 Owners "ETNA", SOC. DI NAVIGAZIONE Owners' Address VIA ALDOVANDI 7, ROME
 UNDER DK 5564 Managers (if not already recorded in Appendix to Register Book)
 NET 3621 Port belonging to PALERMO

Surveyed Afloat or in Dry Dock? BOTH Name of Dock ARSENALE DRY DOCK - SPEZIA Destined Voyage MEDITERRANEAN

Cell DBor DBa feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT tons; MT feet tons.

only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 20909. Port Gen.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case. Head office cable dated 28th December 1954 and subsequent correspondence

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR COMMENCEMENT OF SPECIAL SURVEY, DAMAGE, ALTERATION

Now done for:

1) Commencement of Special Survey (B) due 12.54. Ship 8 years old.

Ship placed in dry dock. Shell plating, sternframe and rudder cleaned, examined and coated. Ship undocked on the 13th July 1955.

EXAMINED: dry cargo hold forward, tween decks, fore and after peak spaces, engine and boiler spaces, under engines and boilers, pump rooms, plating in way of sidelights, overboard scuppers and discharge pipes, cargo suction pipe strums (strums removed), decks with machinery and other casings, P.T.O.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed ...	/	/	/	/	/	/	/	/
Removed and Faird or Repaired	/	/	/	/	/	/	/	/
Faird or Repaired in place	1	/	/	/	/	/	/	/

PRESENT CONDITION OF THE

Decks ...	Good	Bulkheads ...	ply. exam good	Engine Room Skylights ...	good	Copper, or Y.M. (State if on Feil.)	/
Caulking of Decks ...	"	Ceiling ...	good	Coal Bunkers, Openings, Covers, &c.	-	When fitted, Month	Year
Coamings ...	"	Cement or Asphalt ...	"	Oil Bunkers ...	good	Boats ...	not exam
Beams & Fastenings ...	ply. exam good	Rudder ...	"	Scuppers ...	"	Masts, Yards, &c.	good
Outside Plating ...	good	Steering gear and its connections	"	Cargo Hatchways ...	"	Condition, how ascertained (State if wedges removed)	from aloft
" " in way of sidelights	"	Windlass ...	"	Hatches & covers	"	Equipment letter	a+
Frames ...	ply. exam good	Have pumps been examined and found efficient? ...	yes	Planking ...	/	Anchors, No. of	3B+1S
Reverse Frames ...	-	Have Sluice Valves been examined and found efficient? ...	-	Caulking ...	/	Cables (State if now ranged)	yes
Longitudinals ...	good	Have Watertight Doors been examined and found efficient? ...	good	Treenails ...	/	" length 270 fms mean diamr. 52.5 mms (on board)	57.5
Transverses ...	"	Have Ventilators and their Coamings been examined and found efficient? ...	good	Breasthooks & Stemson ...	/	" Rule length 270 fms size 58.5 mms	58.5
Floors ...	ply. exam good	Air and Sounding Pipes ...	"	Transoms, Pointers & Crutches ...	/	Chain Locker ...	good
Keelsons ...	"	Doubling Plates under Sounding Pipes	ply. exam: in order	Timbers of Frame at openings	/	Hawser & Warps ...	good
Stringers ...	"			" " at other places	/	Standing and Running Rigging	"
Inner Bottom Plating ...	"			Stringers, Clamps & Shelves	/	Sails	-
Have the Tanks been examined internally? ...	see SRB			Salting ...	State if examined		
Have the Tanks been tested? ...	see SRB						

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.33," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

This ship, so far as now surveyed, is eligible, in my opinion, to remain as classed with fresh record of docking 7.55 and to have the notation of SS Spz - 7.55 on completion of survey.

COMMENCEMENT OF SPECIAL SURVEY			
Survey Fee (per Section 23)	£ 24.680	179.928	Fees applied for,
CAR FUND	£ 46	1800	17/8/1955
Special Damage or Repair Fee (if any)	£ 46	1800	17/8/1955
Travelling Expenses (if chargeable)	£ 46	46072	Received by me,
LATE JUNE, FEE	£ 46	20.500	19
Second Surveyor's Fee (if any)	£ 46	20.500	
REV. TAX -	£ 46	7.449	

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

010615-010623-0267 1/2

Port of GENOA

(2) Continuation of Report No. 20908 dated
M/TAUER "ANTONIO ZOTTI"

2/8/55

on the

of Special Survey until December 1955, as requested by the Owners.

2) DAMAGE (cause unknown). The following repair now carried out in connection with damage (cause unknown):

- Shell plate No. 2 in 1st strake below sheerstrake (SS fwd), found indented, now satisfactorily faired in place.

3) ALTERATION. Butterworth openings - 320 mm dia - now cut in deck plating in way of cargo tanks and fully compensated by fitting welded steel rings.

CHANGE OF OWNERS & PORT OF REGISTRY:

The vessel has now been sold to Messrs. "ETNA", Soc. di Navigazione, of Palermo.
The new port of registry is Palermo.

Intern Certificate issued - copy attached

superstructures, skylights and companionways, hatchways covers, supports, anchors, chain cables (ranged)^{chain locker}, masts, rigging, steering gear, auxiliary steering gear, windlass, general equipment pumps, W.T. doors, ventilator coverings and covers, air and sounding pipes (striking plates fitted).

Freeboard verified.

EXAMINED INTERNALLY & TESTED: fore peak tank, deep tanks, ~~1~~ lubricating oil double bottom tank, all cargo tanks and forward deep cofferdam

EXAMINED INTERNALLY: O.F. bunkers and settling tanks.

TESTED: after peak tank, O.F. double bottom tank (S.S.)

All parts surveyed found or placed in good condition.

all spaces previously cleared, lining cement and rust removed and spaces cleaned as required. Steelwork afterwards coated as necessary and ceiling, lining and cement replaced.

WEAR & TEAR REPAIRS

Now Done : a few leaky shell rivets in way of after end bulkhead of wing tank

11. 6 (p.s. tanks numbered from aft) now welded and boundary bar of bulkhead in way caulked as necessary.

ITEMS REMAINING TO COMPLETE THE SPECIAL SURVEY:

TO BE INTERNALLY EXAMINED: after peak tank, DF & FW double bottom tanks and cofferdams in way, after deep cofferdam

When Anchors or Cables are supplied, the particulars are to be reported in the following form:

ANCHORS

Number of Certificates.	Anchors.*	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintended.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.			
1st Bower																
2nd "																
3rd "																
Collective Weight																
Stream																
Kedge																

* Where a hammer is used, it should be entered in the column headed "Anchors."

If the certificate name of the place where the anchor was tested is different from the name of the place where it was made, the name of the place where it was tested should be entered in the column headed "Where and when tested and Superintended."

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES

[illegible]

TO BE TESTED: O.T bunkers and settling tanks, O.T double bottom tank (p.s.)
F.W. double bottom tank, after deep expenditure.

As approved by the Committee with telegram dated 28th December 1954, the Owners intend to postpone the completion of the Special Survey until December 1955

all the items required for a General examination, excepting after peak tank, having now been examined and found or placed in order, the Owners' proposal is submitted for the favourable consideration of the Committee. The general condition of the ship, in my opinion, is considered satisfactory for postponement

PLEASE, SEE CONTINUATION SHEET.