

## Report of Survey for Repairs, &amp;c., of Engines and Boilers.

Date of writing Report

19

When handed in at Local Office

(Received at London Office

MAY 15 1940

No. in  
Reg. Book.

Survey held at

Hull

14 MAY 1940

Port of

HULL

Date, First Survey

29. 3. 40

Last Survey

12. 3. 1940

(No. of Visits

27

Year. Month.

When 1919

When 1919

(Donkey) ✓

Owners' Address

(if not already recorded in Appendix to Register Book.)

Port

Voyage

Particulars of Classification (which must be inserted  
precisely as in Register Book & Supplements).

CHARACTER.

Date of last Survey and of  
Periodical Surveys.Machinery and Boiler  
Surveys  
(including date of N.B., if any).

100 A1

Class contemplated

Examined

2.40

Last Report No.

Port

Particulars of Examination and Repairs (if any) *Class contemplated*Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the  
cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on  
account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and  
besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the  
dates and initials of any letters respecting this case.In damage cases where the Surveyor has not made a special damage report he is required to state whether he  
offered his services for this purpose, and why they were declined ✓

Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes*

" " Donkey " " " ✓

If this was not done, state for what reasons? ✓

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the  
Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓State latest date of internal examination of each boiler *P & C 17.4.40. S 30.4.40.*Present condition of funnel(s) *Good*Did the Surveyor examine the Safety Valves of the Main Boiler? *Yes*To what pressure were they afterwards adjusted under steam? *210 lb.*

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓

To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? *Yes*

, and of the Donkey Boilers? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? *Yes*

, and of the Donkey Boilers? ✓

Did the Surveyor examine all the mountings of the Main Boilers? *Yes*

, and of the Donkey Boilers? ✓

Has screw shaft now been drawn and examined? *no*

Is it fitted with continuous liner? ✓

Is an approved appliance fitted at the after end of  
the shaft to permit of it being efficiently lubricated? ✓

Has shaft now been changed? ✓ If so, state reasons.

Has the shaft now fitted been previously used? ✓

Has it a continuous liner? ✓

Is an approved appliance fitted at the after end of  
the shaft to permit of it being efficiently lubricated? ✓

State date of examination of Screw Shaft.

State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft ✓

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light ~~power~~ fitted? *Yes*If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? *no*Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? *no*If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done *To Complete the Survey*The following to examine and first entry particulars obtained:- the main  
engines MP & LP valves, the main engine crankshaft except MP bottom end & LP top end & no 6  
bearing, thrust shaft, screwshaft, sternbush, propeller, sea connections and  
fastenings, Condensers (to test), main and auxiliary pumps except aft independent feed  
and oil fuel transfer pumps, pumping arrangements, main and auxiliary steam  
pipes, dynamos, engines, switchboards, circuits, oil fuel burning installation and  
machinery to try under working conditions.Now Done:- Examined main engine cylinders, pistons & MP valve, MP bottom end,  
LP top end, no 6 main bearing of crankshaft, aft independent feed pump, oil  
fuel transfer pump and intermediate shafting. P.T.O.General Observations, Opinion, and Recommendation:- *The machinery of this vessel, so*(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also  
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.M.S. 9,11, & L.M.C. 9,11, or  
CS 3,34, 140 lb., F.D., &c.)far as seen, is generally in good condition and eligible in our opinion  
to be classed in *completion of classification survey.*

Survey Fee (per Section 29)..... £ : : Fees applied for

Special Damage or Repair Fee (if any)..... £ : : 19

(per Section 29.)

Travelling expenses (if chargeable)..... £ : : Received by me,

19

Committee's Minute

Assigned

See report of

Survey of the hull

FRI 31 MAY 1940

Lloyd's Register

Foundation

010631-010639-0058 1/2

Insert Character of Ship and Machinery precisely as in the Register Book

Is a Certificate required? If so, to be sent to



"EMPIRE GANNET" ex "LOUISIANAN"

Examines boilers internally and externally with all mountings doors and fastenings.

Examines boilers under steam and adjusted safety valves as above.

Generally examines machinery and fire fighting appliances

It was noted that the steam heating pipes passing through the cofferdam were leaking and will require to be renewed or repaired. It was stated this would be done on vessels return to U.K.

W. S. S. & Co.



It is submitted the vessel is  
eligible for the notation  
examined 5.40.

Up to Heating pipes in Copper dam to be  
repaired on return to UK.

GA  
22/5/40

MAINTENANCE OF THE VESSEL  
The vessel is a small motor launch  
built at the Portsmouth Naval Dockyard  
in 1871. It is a 12 foot 6 inch  
launch and is built of copper  
plates. The hull is built of  
copper plates and the bottom  
is built of copper plates. The  
hull is built of copper plates  
and the bottom is built of  
copper plates. The hull is  
built of copper plates and the  
bottom is built of copper  
plates. The hull is built of  
copper plates and the bottom  
is built of copper plates.