

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 24 JUN 1929)

Report of Survey for Repairs, &c., of Engines and Boilers. (Received at London Office 24 JUN 1929)

Date of writing Report 20/6/1929 When handed in at Local Office 20/6/1929 Port of Bilbao.

Survey held at Bilbao. Date, First Survey 14/6/29 Last Survey 20/6/1929 (No. of Visits 2)

7683 on the Machinery of the Wood, Iron or Steel Ss. "CILURNUM"

Age { Gross 3077 Net 1848 Vessel built at Middlebro' By whom S. Payton Dixon & Co Ltd When 1919

Engines made at Middlebro' By whom Redmonds & Co Ltd When 1919

Boilers, when made (Main) 1919 (Donkey) -

Owners Antonio Menchaca Owners' Address 28 Avenida Port Bilbao Voyage CARDIFF

Managers If Surveyed Afloat or in Dry Dock P. N. N. (State name of Dock.)

Donkey Boilers

Report No. Port

Particulars of Examination and Repairs (if any) Complete

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined?

Has a damage report made by anyone else? If so, by whom?

Has the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Donkey " " " "

Was not done, state for what reasons?

What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Has the Surveyor examine the Safety Valves of the Main Boiler? Yes under steam. To what pressure were they afterwards adjusted under steam? 180 lbs/2"

Has the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Has the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? , and of the Donkey Boiler?

Has the Surveyor examine the drain plugs of the Main Boilers? , and of the Donkey Boiler?

Has the Surveyor examine all the mountings of the Main Boilers? , and of the Donkey Boiler?

Has screw shaft now been drawn and examined? Is it fitted with continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has shaft now been changed? If so, state reasons

Has the shaft now fitted been previously used? Has it a continuous liner? Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated?

Has the distance between ligum vitae or bearing metal of stern bush and top of after bearing of screw shaft?

Has Survey is not complete, state what arrangements have been made for its completion and what remains to be done? Complete.

Now Done: [PLEASE SEE HULL REPORT N°39691 + LONDON-GENOA LETTER 10/5/29]

Steel main boiler examined under steam, safety valves adjusted to 180 lbs.

Pumping arrangements verified from approved plan & examined.

The water end valves of the auxiliary feed pump examined & overhauled.

A spare set of bridge pump valves now supplied.

In addition to the above the windlass & steering engine have now been examined throughout.

General Observations, Opinion, and Recommendation:— The machinery of this vessel is (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)

Now seen to be in safe working condition and eligible in my opinion to remain as classed & recommended.

Survey Fee (per Section 28) £ : : Fees applied for 19

Additional Damage or Repair Fee (if any) £ : : Received by me, 19

Printing Expenses (if chargeable) £ : :

Committee's Minute TUE. 2 JUL 1929

Signed Line MS 3. 29

ARTIFICATE WRITTEN 3. 29 CL

Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

Classification survey completed.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD.

L.M.C. ~~4.29~~ M.S. 3.29
S.3.29 B.S. 4.29
C-L 3SB 180 lb.
NHP 362.

28/6/29

J. J.

[Faint handwritten notes and bleed-through from the reverse side of the page are visible across the main body of the document.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021
Lloyd's Register
Foundation