

9. No. 378196
REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS
(Received at London Office) 12 JUN 1954

Date of writing Report 25-5-54 When handed in at Local Office 19-54 Port of Rotterdam
Book. Survey held at Rotterdam Date First Survey 18th March Last Survey 14th May 1954
(No. of Visits)
2774 on the Machinery of the Wood Iron or Steel Tw. Se. m/l. VAN DER STENG "Now, REGILUM"
Age { Gross 299 Vessel built at Schiedam By whom M. J. Willem - Fuenoord When 1948 6
Net 74 Engines made at Angelo By whom G. B. B. P. R. N. 1. When 1948
As Per Rule 104 Boilers, when made (Main) (Donkey)
Main Boilers Owners Carlo Cameli Armatoe Owners' Address Via Roma 1, Genova
(if not already recorded in Appendix to Register Book.)
Donkey Boilers Managers Port Genoa Voyage
If Surveyed Afloat or in Dry Dock Both
(State name of Dock.) Willem - Rotterdam
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. Port
Particulars of Examination and Repairs (if any) Rep. LMC TS Repair
Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and details of any letters respecting this case.

Where cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.
If damage report made by anyone else? If so, by whom?
Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?
Donkey
state for what reasons? What parts of the Boilers could not be thus thoroughly examined?
special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?
latest date of internal examination of each boiler? Present condition of funnel(s) Efficient

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?
Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?
Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?
Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?
Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?
Were screw shafts now been drawn and examined? Yes Has it a continuous liner? No Is an approved oil retaining appliance fitted at the after end? Yes
Has the shaft now fitted been previously used? Yes Has it a continuous liner? Yes
approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft Both 5-4-54 State the wear down in the
r bush minimum Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? Yes
the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes
the parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete
IN DONE:- Vessel placed on slipway, propellers, oil glands, stem tube bushes, sea valves (ground) and external fastenings examined and found or replaced in efficient condition. Both tail shafts drawn, examined and found in order.
MC:- Examined all Port and Starboard M.E. cylinder liners, covers, valves and valve gear, pistons, gudgeon pins and brasses, connecting rods, bottom end bearings and pins, main bearings and journals, thrusts and reversing couplings, intermediate shafting and bearings, Port and Starboard auxiliary engines in their entirety, both aux compressors, both starting air receiver (tested), and attached pumps, bilge pump, G.S. pump, pumping arrangements, L.O. pumps, daily service tanks, electrical equipment and all found or replaced in efficient condition. All machinery examined under working conditions.

REPAIRS:- W.T. Blades of both propeller fixed. New cylinder block fitted to Starboard aux engine, No 1 & 2 main bearings of Port M.E. re-metalled & several minor wear & tear repairs also effected at this time
General Observations, Opinion, and Recommendation:-
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The Machinery of this vessel as now seen is in efficient condition and in my opinion, eligible to remain as classed with first records + LMC CS 5,54 and TS 4,64.04.

Survey Fee (per Section 23) 240.- Fees applied for, 9.6.19.54
Damage or Repair Fee (if any) 60.- Received by me, 19.54
(per Section 23.) ELECT. 110.-
Printing expenses (if chargeable) 10.50
Committee's Minute 17 AUG 1954
Signed Wide Rbt. 8.

Is a Certificate required? If so, to be sent to Rotterdam office.

W. Armatoe
Engineer Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

010727 - 010733 - 0105