

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

28 MAY 1953

24 JUN 1953
LIVERPOOL

Date of writing Report... 19... When handed in at Local Office... 19... Port of... LIVERPOOL

Survey held at... ELLESMERE PORT Date... First Survey... 17 April Last Survey... 21 May 1953 (No. of Visits... 2)

on the Machinery of the Wood, Iron or Steel... M.V. 'CASTLEGATE'

Gross 51 Vessel built at Northwich By whom W. J. Yarwood & Sons, Ltd. Year. 1928 Month. 1
 Net 28 Engines made at Dagenham By whom Russell Newbery & Co. Ltd. When 1949
 12 Boilers, when made (Main) - (Donkey) -
 Owners Esso Petroleum Co. Ltd. Owners' Address
 (if not already recorded in Appendix to Register Book.)
 Main Boilers - Managers - Port Liverpool Voyage
 Donkey Boilers -
 Pressure - If Surveyed Afloat or in Dry Dock Both
 Main Boilers - (State name of Dock.) Canal and on Ellesmere Port Pontoon

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Years assigned now or expired.	Machinery and Boiler Surveys (including date of N.E., if any)
*Al Barge 3,52.		*LMC 5,52.
ss Liv.-2,51.		*NE 49.
		TS.CL.3,52.
		Oil Eng.

For Canal & Inland Waterways service. Carrying Petroleum in portable tanks.

Report No. Port Particulars of Examination and Repairs (if any) Obj 0 with. for annual certif.

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides stated in the body of the report, should be briefly summarised at the end of the report. State also the dates and of any letters respecting this case.

In those cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Damage report made by anyone else? If so, by whom? Surveyor personally go inside each Main Boiler separately and make a through examination at this time?

State for what reasons? What parts of the Boilers could not be thus thoroughly examined?

Special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Test date of internal examination of each boiler? Present condition of funnel(s).

Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Screw shaft now been drawn and examined? No Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

Approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft State the wear down in the bush 3/32 Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? Yes

Insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes.

Parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Work done for M.S.C. annual certificate: Vessel on pontoon, propeller & outside fastenings examined and found in order.

Examined, M.E. cylinders, covers, valves, pistons, con-rod bearings, crankshaft, also the auxiliary engine in its entirety.

The clutch and reverse gearing generally examined without opening out. Machinery examined under working conditions; found in order.

The electrical installation examined megger tested & found satisfactory. Aux. engine main bearings renewed. Deck electrical cables renewed.

Observations, Opinion, and Recommendation:— P.T.O.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and so any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, *LMC 9,11 or LMC 140 lb., FD, &c.)

Eligible in our opinion to remain as classed without fresh record of survey. Subject items, renew aux. engine cyls by 5,54.

Also eligible to have the annual certificate renewed for barges carrying petroleum spirit on the Manchester Ship Canal, in conjunction with report on barge.

Fees applied for, 16.6. 19.53 Received by me, N. Chambers, C. Reed

Expenses (if chargeable) £1:13:8 Engineer Surveyor to Lloyd's Register of Shipping.

LIVERPOOL 23 JUN 1953

As now, subject



Insert Character of Ship and Machinery precisely as in the Register Book

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

If Stockless, state Mechanical Test.

Is a Certificate required? If so, to be sent to

REPORT OF SURVEY FOR REPAIRS OF ENGINES AND BOILERS

S. R. 6 Owners have not yet obtained new cylinders for the auxiliary engine. The engine continues efficient for a further 12 mos. period.

[Faint, mostly illegible handwritten notes and bleed-through from the reverse side of the page.]

[Faint, mostly illegible handwritten notes and bleed-through from the reverse side of the page.]

[Faint, mostly illegible handwritten notes and bleed-through from the reverse side of the page.]

[Faint, mostly illegible handwritten notes and bleed-through from the reverse side of the page.]

Noted
Lloyd as not recommended
for
20.6.13

