

## REPORT OF SURVEY FOR REPAIRS, &amp;c., OF ENGINES AND BOILERS

17 SEP 1952

(Received at London Office)

Date of writing Report 15th August, 1952 Port of BremenNo. in Survey held at Bremerhaven Date. First Survey 26th June 1952 Last Survey 14th August 1952Reg. Book 95362 S (No. of Visits 9)on the Machinery of the Wood-broker Steel S.S. "S.N.A. 6", ex "CHEPO", ex "LUMBERMAN"Tonnage Gross 2877 Vessel built at St. John N.B. By whom St. John D.D. & S.B. Co. Ltd. When 1943 5Net 1655 Engines made at Montreal By whom Dominion Bridge Co. Ltd. When 1943 5Nominal 200 Boilers, when made (Main) 1943/5 mo. (Donkey)No. of Main Boilers 2 Owners Societe Nationale d'Affretements Owners Address (if not already recorded in Appendix to Register Book.)No. of Donkey Boilers - Managers - Port Rouen Voyage ReparationsSteam Pressure in Main Boilers 200 lbs If Surveyed Afloat or in Dry Dock Both (State name of Dock.) (Norddeutscher Lloyd)Last Report No. Port Particulars of Examination and Repairs (if any) BS, TS CL, SRL

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom? yesDid the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? yesIf not, state for what reasons - What parts of the Boilers could not be thus thoroughly examined? -What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? -State latest date of internal examination of each boiler p. 30.7.52, s. 31.7.52 Present condition of funnel(s) efficientDid the Surveyor examine the Safety Valves of the Main Boilers? yes To what pressure were they afterwards adjusted under steam? 200 lbsDid the Surveyor examine the Safety Valves of the Donkey Boilers? - To what pressure were they afterwards adjusted under steam? -Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? yes and of the Donkey Boilers? -Did the Surveyor examine the drain plugs of the Main Boilers? - and of the Donkey Boilers? -Did the Surveyor examine all the mountings of the Main Boilers? yes and of the Donkey Boilers? -Has the screw shaft now been drawn and examined? yes Has it a continuous liner? yes Is an approved oil retaining appliance fitted at the after end? noHas shaft now been changed? no If so, state reasons - Has the shaft now fitted been previously used? - Has it a continuous liner? -Is an approved oil retaining appliance fitted at the after end? - State date of examination of Screw Shaft 29.7.52 State the wear down in the stern bush running fit Is electric light and/or power fitted? yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? noHas the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? no Engine parts, when referred to by numbers, should be counted from forward. complete

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

NOW DONE:-

Vessel placed in dry-dock, examined propeller and outside fastenings, sea valves (opened), screw shaft (drawn), stern bush.

Examined port and starboard boilers in their entirety together with their superheaters, mountings, doors, and fastenings. Safety valves adjusted under steam to 200 lbs. Boiler front O.F. pressure pipes examined under working conditions, fire extinguishing apparatus examined and tested, deck controls to O.F. and steam valves examined and tested all with satisfactory results.

Repairs: Bottom half of stern bush rewooded.

A few tubes in each boiler re-expanded. One stoppered tube in port boiler renewed.

Two stay tubes in starboard boiler renewed (leaking).

Two side stays in starboard boiler renewed (fractured).

Water gauge cock controls and guards renewed.

Longitudinal welds in the following furnaces veed out and electric welded: -

General Observations, Opinion, and Recommendation:— The machinery of this vessel is in good order and eligible

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &amp;c.; thus, for example, BS 9.11, B&amp;MS 9.11 or LMC 9.11 or LMC 140 lb., FD, &amp;c.)

in my opinion to remain as classed in the Register Book with fresh record of B.S. 8.52 and T.S. CL 7.52

Survey Fee (per Section 23) BS 15 : 0 : 0 TS CL 5 : 0 : 0 Repairs 10 : 0 : 0Special Damage or Repair Fee (per Section 23.) £ 9 : 0 : 0Travelling expenses (if chargeable) £ 9 : 0 : 0Committee's Minute BS 8.52Assigned S 7.52Alfred Bremer  
Engineer Surveyor to Lloyd's Register of Shipping.Lloyd's Register  
Foundation

010835-010845-0154



Starboard boiler centre furnace No.3 corrugation from forward. See page 102

The defects now repaired in the furnaces were slight. The original weld had not opened but from

It is recommended that the furnace lap welds be kept under observation at next B.S.

Voyage Repairs: -

L.P. and M.P. eccentric straps (top halves) re-white metallised (wear).

Alterations: Port and starboard ballast tanks now fitted in tween decks. 2 1/2" stripping line connected to ballast tanks.

10/10/66  
pump and 6" overboard discharge line connected to ballast pump overboard discharge line. Work completed satisfactorily.

Vessel changed name and ownership as follows: -

To "CHEPO", Port of Registry, Panama R.P., new Owners Thallata S.S. Co., London.

To "S.N.A.6", Port of Registry, Rouen, new Owners Societe Nationale d'Affretements.

- W. H. G. A. Km.

entitled

200 fpa

Yes

295

297

on

tit grüner

complete

HOW LONG:-

Vessel placed in dry-dock, examined propeller and outside fastenings, sea valves (opened), screw shaft

all with satisfactory results.

Conditions, fire extinguishing apparatus examined and tested,  
and testings. Safety valves adjusted under steam to 200 lbs.  
Boiler front O.F. pressure pipes examined under working  
Examined port and starboard boilers in their entirety together with their superheaters, mountings, doors,

Repairs: Bottom half of stern bush rewooded.

A few tubes in each boiler re-expanded. One stoppered tube in port boiler renewed.

Two stay tubes in starboard boiler renewed (leaking).

Two side stays in starboard boiler renewed (fractured).

Water gauge cock controls and guards renewed.

Longitudinal welds in the following furnaces used and electric welded: -

The machinery of this vessel is in good order and reliable

in my opinion to remain as classed in the Register Book with fresh record of B.2. 8.32 and T.2. CL 7.32

0	0	12	HS
0	0	5	TS CL
0	0	10	Reverts
0	0	2	