

One H.P. eccentric - ring fitted with new white metal.

H.P. cross-head forward bearing fitted with new white metal.

F.P. piston rings renewed.

One F.P. eccentric - ring fitted with new white metal.

L.P. slide - rod skimmed in lathe, gland and neck bushes renewed.

One L.P. eccentric - ring fitted with new white metal.

Two feed - pump plungers skimmed in lathe.

The fan - engine fitted with new piston - rings and the piston - rod skimmed in lathe.

All condenser tubes removed, tested and replaced, 10 tubes renewed.

The water cylinders of the donkey pump rebored and the pistons fitted with lining of white metal.

The bath furnaces of the Port Boiler were found to be pressed down and have now been restored and strengthened by three electric - welded collars $4" \times \frac{3}{4}"$.



© 2021

Lloyd's Register
Foundation