

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "KURWINA" REPORT MCH No. 327.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee’s Report, 24/5/92.*)

Type of Engine 2 Oil Engines 4 S.C.S.A. through S.R. Reverse gears to 2 Screwshafts.

each 8 cylinders  $5\frac{1}{2}"$  x  $7\frac{3}{4}"$ .

M.N. 40

B.H.P. 198

~~XXXXXXXXXXXXXsXXXXXXwithXXXXXXnaught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of approved type YES  
(B).

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letters dated 10.10.60 and 16.6.61 for an engine speed of 900 R.P.M. and corresponding propeller speed of 300 R.P.M.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 5.61.

Classification Certificates not to  
be issued until a satisfactory  
General Examination reported after  
arrival in the Service Area.

© 2021

Lloyd's Register  
Foundation

010846-010857-0212