

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office.....)

Date of writing Report 5 Feb. 10 #1 When handed in at Local Office 7 Feb. 10 #1 Port of GARDIFF

Survey held at Penarth Date. First Survey 16 Jan 41 Last Survey 30 Jan 1941
(No. of Visits 2)

074 on the Machinery of the Wood Iron or Steel Sc "Mari II"

Age { Gross 1395 Vessel built at Haarlem By whom N.V. Werf Bourad When 1918
Net 811 Engines made at Hengelo By whom Geb. Stork & Co. When 1918

Final Horse Power 133 Boilers, when made (Main) (Donkey)

of Main Boilers 2 Owners Ministry of Shipping Owners' Address Glasgow

of Donkey Boilers 1 Managers Shamrock Shipping Co. Ltd Port Glasgow Voyage Voyage

Working Pressure—Main Boilers 156 If Surveyed Afloat in Dry Dock Penarth Pontoon Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. General Port Penarth

Particulars of Examination and Repairs (if any) Examination

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be briefly summarised at the end of the report. State also the names and initials of any letters respecting this case.

Where damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined.

Was a damage report made by anyone else? If so, by whom? No

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Was this done, state for what reasons? Boilers not prepared for survey.

What parts of the Boilers could not be thus thoroughly examined? Boilers not prepared for survey.

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? Yes

State latest date of internal examination of each boiler. Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boiler? (under steam) Yes To what pressure were they afterwards adjusted under steam? 156 #0

Did the Surveyor examine the Safety Valves of Donkey Boiler? Yes To what pressure were they afterwards adjusted under steam? 156 #0

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? (under steam) Yes and of the Donkey Boilers? Yes

Did the Surveyor examine the drain plugs of the Main Boilers? Yes and of the Donkey Boilers? Yes

Did the Surveyor examine all the mountings of the Main Boilers? (under steam) Yes and of the Donkey Boilers? Yes

Has the screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Has shaft now been changed? No If so, state reasons. Yes Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

Has the shaft now fitted been previously used? Yes Has it a continuous liner? No Is an approved appliance fitted at the after end of the shaft to permit of it being efficiently lubricated? No

State date of examination of Screw Shaft. 16.1.41 State the distance between lignum vitae or bearing metal of stern bush and top of after bearing of screw shaft. Close

Engine parts, when referred to by numbers, should be counted from forward. Is electric light and compass fitted? Yes

Did the Surveyor examine the generators, ~~motors~~, switchgear, cables and fuses? (under working conditions) Yes

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? No

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done.

Now done. Vessel placed on a pontoon; examined propeller, stern tube & bush, sea connections and fastenings. The screw shaft drawn in and examined; this is fitted with four sections of liners of equal length fitted butt to butt and giving an overall length of 11'6". The liners are pegged; the diameter of the shaft under the liner is 11 1/2" and the least diameter of liner is 12 1/16".

Generally examined main engines, auxiliary pumps and elec. lighting system (the 2 latter under working conditions). Examined main boilers (2) under steam and adjusted their safety valves to 156 #0; the official W.P. previously approved by Bureau Veritas. Forwarded herewith is the B.V. certificate of Classification No 101414 concerning the machinery and boilers.

General Observations, Opinion, and Recommendation:— The machinery and boilers of this vessel as now seen, are in an efficient condition and eligible in my opinion, for "class contemplated". Consideration might also be given to the notation of T.S. 1,41.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,11, B.&M.S. 9,11, *L.M.C. 9,11, or *L.M.C. 140 lb., F.D., &c.)

CS 3,34,

CS 3,34,

CS 3,34,

CS 3,34,

Survey Fee (per Section 29) £ : /

Special Damage or Repair Fee (if any) (per Section 29.) £ : /

Travelling expenses (if chargeable) £ : /

Committee's Minute See Aft. on hull

Assigned See Aft. on hull

Survey Fee (per Section 29) £ : / Fees applied for 19. Received by me, 19.

B. Knoffatt.
Engineer Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

010982-010991-0068

Insert Character of Ship and Machinery precisely as in the Register Book

Survey for classification commenced
Washington generally examined
to show & also connections
examined.

Examined 4/11/41 for
18 mos.
4/1/41

Submitted to Surveyor & asked to
state what steps were taken to
comply with the instructions
in the Secretary's letter 10/1/41
Par. 3 regarding the
machinery
4/3/41.

[Faint handwritten notes and bleed-through from the reverse side of the page, including phrases like "examined", "connections", and "machinery".]