

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 10 FEB 1956)

Port of KOBE

Date of writing Report 23rd Jan., 1956.

When handed in at Local Office JAN 31 1956

Date First Survey 5th Jan., Last Survey 13th Jan., 1956.

(No. of Visits 4)

Survey held at Mukaishima on the Machinery of the ~~XXXXXX~~ Steel S.S. "LIVERPOOL MARU"

Gross 6463  
Net 3918  
As Per Rule 700  
of Main Boilers 3  
" " " 8611  
of Donkey Boilers 1  
Main Boilers 200  
Donkey Boilers 200

Vessel built at Wsm.

By whom J.C. Tecklenborg

When 1922

Engines made at "

By whom (Donkey)

When

Boilers, when made (Main)

Owners Daiichi Kisen K.K.

Owners' Address (if not already recorded in Appendix to Register Book.)

Port Kobe

Voyage

Managers

If Surveyed Afloat or in Dry Dock Hitachi, Mukaishima S.Y.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

HULL

MACHINERY

100A1

SS 5,50

Dkg - 6,55

LMC 12,54

BS 12,54

CL 10,53 N

sps 12,54

st Report No. Port BS &amp; G.E. of Machy.

Particulars of Examination and Repairs (if any) State clearly the Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. Repairs on of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides g detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and tals of any letters respecting this case

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

a damage report made by anyone else? If so, by whom?

the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Aux. Yes

What parts of the Boilers could not be thus thoroughly examined?

at special means, in the absence of internal examination, were adopted by the

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? 5-1-56

the latest date of internal examination of each boiler Present condition of funnel(s) Good

the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under steam? 206 lbs/in<sup>2</sup>

the Surveyor examine the Safety Valves of the Donkey Boilers? Yes To what pressure were they afterwards adjusted under steam?

the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? Yes and of the Aux. Boilers? Yes

the Surveyor examine the drain plugs of the Main Boilers? Yes and of the Aux. Boilers? Yes

the Surveyor examine all the mountings of the Main Boilers? Yes and of the Aux. Boilers? Yes

the screw shaft now been drawn and examined? No Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

shaft now been changed? If so, state reasons Has the shaft now fitted been previously used? Has it a continuous liner?

an approved oil retaining appliance fitted at the after end? State date of examination of screw shaft State the wear down in the

tern bush 4.5m/m Is electric light and/or power fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear cables and fuses? Yes

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms?

the parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

the Survey is not complete, state what arrangements have been made for its completion and what remains to be done. Complete.

Now Done:- Ship placed in drydock, propeller, aft end of stern bush, sea connections &amp; valves with their shell fastenings, examined and found in good condition.

Engine opened up for survy:- All cylinders (covers opened up) and crank, thrust shaft, pumps and condensers (tested), opened up examined and found or now placed in good condition.

Exhaust turbine, shaft bearings and gearing examined as far as practicable and found in good condition.

S.S.:- The 3 Main and 1 Auxiliary Boilers with superheaters on the Main boilers examined internally and externally with doors, mountings, fastenings and safety valves and found or now placed in good condition. Safety valves adjusted under steam as stated above.

Oil fuel and steam smothering installations tested under working conditions fuel tank valves, deck control gear, and oil discharge pipes between pumps and furnaces generally examined and found in good condition.

NOTE:- Circulating pump casing holed at bottom of lower casing, now covered with doubling from inside.

REPAIRS DUE TO WEAR AND TEAR:- New surface feed water heaters fitted. Same hydraulically tested by 2 x W.P. P. boiler - 1 smoke tube renewed.

Other minor repairs and adjustment effected.

Interim Certificate No. B1-28272 issued - copy attached.

General Observations, Opinion, and Recommendation:-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The Machinery and boilers of this ship, are in good condition and eligible in my opinion

to be continued as classed with fresh record of BS 1,56, subject to main circulating pump casing

being renewed before the end of January, 1957.

Survey Fee (per Section 23) B.S. \$46,000

Special Damage or Repair Fee (if any) G.E. of Machy 10,000

Travelling expenses (if chargeable) 3,500

Committee's Minute TUESDAY 28 FEB 1956

Signed As above, subject BS 1,56

Engineer Surveyor to Lloyd's Register of Shipping.

© 2021 Lloyd's Register Foundation