

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 31-3-55 1955 When handed in at Local Office 31-3-55 1955 Port of MELBOURNE

No. in Reg. Book Survey held at MELBOURNE Date, First Survey 4-3-55 Last Survey 29-3-55 1955
(No. of Visits Five)

18095 on the Wood, Iron or Steel S.S. "LOWANA"
 68222
 TONNAGE:— Built at Port Glasgow By whom Dunlop, Bromner & Co.Ltd. When YEAR 1924 MONTH 6
 GROSS 3039 Owners G. Grimble & Co. Ltd. See Surveyors letter
 UNDER DK. 2659 Owners' Address Melbourne S.S.Co.Ltd. 2-4-55 (if not already recorded in Appendix to Register Book)
 NET 1697 Managers -do- Port belonging to MELBOURNE

Surveyed Afloat or in Dry Dock? Both Name of Dock Duke's & Orr's Destined Voyage _____

CellDBorDBa _____ feet; uE&B _____ feet; f _____ feet } Particulars of Classification (which must be inserted
 total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons. } precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.
 N.B.—All Alterations in the existing records should be underlined.

CHARACTER * for Special Survey	Machinery and Boilers Surveyed
-----------------------------------	-----------------------------------

last Report, No. 157. Port Wemy.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case).

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. _____

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Machinery and Boiler Surveys (including date of N.B., if any)
*100A1	*LNC
shelter deck	B.S. 11, 53
with freeboard	M.S. 12, 49
12, 53	TS WA 11, 52 CL
SS MEL 12, 49 (Dr.)	
CARGO BATTENS NOT FITTED	
Laid Up - Surveys Overdue.	
Society's Freeboard (if assigned) { painted on Ship and now verified {	ft. ins.

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR General Examination
The Secretary's Letters dated 2-2-55 (ClassnH) and 11-2-55 (Fbd).
This Vessel placed in dry dock, shell plating, rudder and sternframe cleaned, examined, found
in good condition and recoated.
Ash shoot and other shell openings examined. All holds and tween decks, examined, the
bilge limbers lifted and strums and pumping arrangements tested.
The bunker tween decks examined and lower bunkers in way of shell plating and bilges.
The forward and after peak tanks examined internally and afterwards tested.
The rods, chains, sheaves and fastenings of the steering gear examined and the steering gear
and windlass afterwards tested.

(See over)

STORY OF DAMAGE REPAIRS:—	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Beams	Inner Bottom Plates	Dk. Plates	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

ENT CONDITION OF THE							
Good		Bulkheads	Good	Engine Room Skylights	Good	Copper, or Y.M.	
ing of Decks	Good	Ceiling	Good	Coal Bunkers, Openings, Covers, &c.	Good	(State if on Felt)	
ngs	Good	Cement or Asphalt	Good	Oil Bunkers	-	When fitted: Month	Year
& Fastenings	Good	Rudder	Good	Scuppers	Good	Boats	Good
le Plating	Good	Steering gear and its connections	Good	Cargo Hatchways	Good	Masts, Yards, &c.	Good
" In way of sidelights	Good	Windlass	Good	Hatches	Good	Condition, how ascertained	from deck
s	Good	Have pumps been examined and found efficient?	Yes	Planking	-	(State if wedges removed)	
e. Frames	Good	Have Sluice Valves been examined and found efficient?	-	Caulking	-	Equipment letter	
udinals	-		-	Treenails	-	Anchors, No. of	3B 1S
orses	-	Have Watertight Doors been examined and found efficient?	Yes	Breasthooks & Stemson	-	Cables (State if now ranged)	NO
ns	-		-	Transoms, Pointers & Crutches	-	" length	- mean diamr. -
rs	-	Have Ventilators and their Coamings been examined and found efficient?	Yes	Timbers of Frame at openings	-	(on board)	-
Bottom Plating	Good		-	" " at other places	-	" Rule length	- size -
he Tanks been examined Internally?	peaks only	Air and Sounding Pipes	Good	Stringers, Clamps & Shelves	-	Chain Locker	
he Tanks been tested?	peaks only	Doubling Plates under Sounding Pipes	Yes	Salting	-	Hawser & Warps	Stated sufficient
				(State if examined)		Standing and Running Rigging	Good
						Sails	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"..... to remain as classed in the Register Book *without fresh record of Survey*," "to remain as classed and to have record of survey, 133," or "to remain as classed and to have record of survey, 138, and the notations of ss No. 138."

This vessel is now in good condition, eligible for record of Docking
urvey 3,55 and fit for a voyage to a Japanese Port via Manilla.

Fee (per Section 29).....	2	60	:	0	:	0	Fees applied for,
le Charges							
Damage or Repair Fee (if any).....	2	7	:	18	:	0	30-3-1955
per Sec. 29)							Received by me,
no Expenses (if chargeable).....	2	4	:	5	:	0	19
Surveyor's Fee (if any).....	2	1	:	1	:		

THURSDAY - 9 JUN 1955

mittee's Minute.

acter designed

Noted
for
Header

011140-011148-0083

Surveyor to Lloyd's Register of Shipping

TUESDAY 28 JUN 1955

add Class suspended
to Laid up & Nation

Is Certificate required? If so, to be sent to _____

REPAIRS Fifteen hatch cleats renewed, three wood hatch covers renewed and four repaired. Saddle back hatch coaming rest bars faired. Starboard sounding pipe to No. 1 hold bilges renewed. One tank side bracket in E.R.p.s. adjacent to main injection valve cropped and part renewed. Section of No. 1 Hold bilge suction in starboard bunkers renewed.

Fifteen hatch cleats renewed, three wood hatch covers renewed and

Saddle back hatch coaming rest bars faired. Starboard

One tank side bracket in E.R.p.s.

Section of No. 1 Hold bilge suction in starboard bunkers renewed.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS

ANCHORS																Where and when tested and Superintendent	
Number of Certificate	Anchors*	Weight, Ex. Stock			Weight of Stock			Test per Certificate				Weight Required by Rule			Description of Anchor	Makers	
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream																
	Kedge																

* When a bower anchor is supplied, it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES

[illegible]

Iron Stream Chain
or Steel Wire

GENERAL COMMITTEE

22.3 September
Classing Committee's
decision confirmed.