

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

No. 133233

Date of writing Report..... 19..... When handed in at Local Office **22 JUN 1951** Port of **LIVERPOOL**

Survey held at **Ramsey Isle of Man.** Date. First Survey **11/4/51** Last Survey **1/5/51**

on the Machinery of the **Wood, Iron or Steel** **S.S. MANIVIN.** (Grab Hopper Dredger) (No. of Visits **3**)

Gross **123** Vessel built at **Renfrew** By whom **Lobnitz & Co. Ltd.** Year **1936** Month **5**

Net **43** Engines made at **do.** By whom **do.** When **1936**

Principal Power **140** Boilers, when made (Main) **1936** (Donkey) **-** When **1936**

Owners **Isle of Man Harbour Commissioners** Owners' Address **-**

Managers **-** (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock **Both** Port **Douglas I of M** Voyage **-**

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Report No. **1S** Port **Douglas I of M**

of Examination and Repairs (if any) **M.S., B.L.R.S., & msp.**

When held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent Repairs. Repairs on the body of the report, should be briefly summarised at the end of the report. State also the dates and matters respecting this case.

where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined. **No damage repaired**

port made by anyone else? If so, by whom? **Yes**

personally go inside each Main Boiler separately and make a through examination at this time? **Yes**

Donkey **None**

What reasons? **✓** What parts of the Boilers could not be thus thoroughly examined? **11-4-51**

Plans, in the absence of internal examination, were adopted by the Surveyor to ensure himself of the thorough efficiency of those parts of each Boiler? **✓**

of internal examination of each boiler **11-4-51**

or examine the Safety Valves of the Main Boilers? **Yes** Present condition of funnel **Good**

or examine the Safety Valves of the Donkey Boilers? **✓** To what pressure were they afterwards adjusted under steam? **140 lbs.**

or examine all the manholes, doors and their fastenings of the Main Boilers? **Yes** To what pressure were they afterwards adjusted under steam? **✓**

or examine the drain plugs of the Main Boilers? **None** and of the Donkey Boilers? **✓**

or examine all the mountings of the Main Boilers? **Yes** and of the Donkey Boilers? **✓**

Shaft now been drawn and examined? **No** Has it a continuous liner? **✓** Is an approved oil retaining appliance fitted at the after end? **✓**

been changed? **✓** If so, state reasons **✓** Has the shaft now fitted been previously used? **✓** Has it a continuous liner? **✓**

oil retaining appliance fitted at the after end? **✓** State date of examination of Screw Shaft **✓** State the wear down in the

on resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? **✓**

when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

is not complete, state what arrangements have been made for its completion and what remains to be done. **Complete**

now **Examined propeller oil gland without dismantling, sea connections and their fastenings.**

:- **Examined Main Engine LP cylinder pistons, bottom end bearing and crankpin HP&LP slide-valves and casings. NO3 main bearing and crankshaft journal Independent feed pumps. Independent bilge pump. Main steam pipes tested to 280 lbs.**

S.:- **Examined Boilers internally and externally together with safety valves, mountings manholes doors and their fastenings Safety valves adjusted under steam.**

Minor repairs carried out.

Observations, Opinion, and Recommendation. —

State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, & LMC 9,11 or

machinery of this vessel so far as now seen is eligible in our opinion to be entered in as cleared with fresh record of MBS* 5,51 now, B.L.R.S. 5,51 now and msp

per Section 29) Ins. **10:0:0** Fees applied for **22 JUN 1951**

Age or Repair Fee (if any) **4:0:0** Received by me, **H. Lloyd for self and A.M. Kennedy**

Expenses (if chargeable) **6:6:6** 19. **Engineer Surveyor to Lloyd's Register of Shipping.**

LIVERPOOL **26 JUN 1951**

MBS* 5,51 B.L.R.S. 5,51

M.S.P. 4,51

Lloyd's Register Foundation

011273-011274-0084