

22 AUG 1955

No.

2094

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 3-8 1955 When handed in at Local Office 3-8 1955 Port of GENOA
 No. in Survey held at SPEZIA Date, First Survey 17-7-55 Last Survey 21-7 1955
 59094 on the Wood, Iron or Steel STANKER "ENRICO INSOM" (No. of Visits 5)
 TONNAGE: — Built at PORTLAND, OR By whom KAISER CO. INC. When 1944 MONTH —
 GROSS 10427 Owners ENRICO INSOM Owners' Address —
 UNDER DK. 9421 Managers — (if not already recorded in Appendix to Register Book)
 NET 6250 Port belonging to ROME

Surveyed Afloat or in Dry Dock? BOTH Name of Dock ARSENALE DRY DOCK - SPEZIA Destined Voyage —
 Cell DBor DBa — feet; uE&B — feet; f — feet
 total capacity — tons. FPT — tons; APT — tons; MT — feet. tons.
 only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 140824 Port Liv.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form State also the dates and initials of any letters respecting this case

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

not required

Was a damage report made by anyone else? if so, by whom? by Underwriters' Surveyor.

REPAIRS, OR EXAMINATION AS PER RULE FOR DOCKING & DAMAGE

Now done for:

1) DOCKING. Ship placed in dry dock. Shell plating, stern frame and rudder cleaned, examined and coated Ship undocked on the 20th July 1955.

EXAMINED: weather decks, hatchways with their closing and securing appliances, ventilators and other deck openings, casings and superstructure bulkheads with their closing appliances, windlass, general equipment, main and auxiliary steering arrangements, cargo tanks No 3 (port side), 7 (port and starboard) & 8 (centre).

All parts surveyed found or placed in good condition excepting as reported below.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—	P.T.O.
Renewed ...	/	/	/	/	/	/	/	1 side transverse web (port)	
Removed and Fairled or Repaired	/	/	/	/	/	/	/	—	
Fairled or Repaired in place ..	2	/	/	/	/	/	/	2 side transverse webs.	

PRESENT CONDITION OF THE

Decks ... good	Bulkheads part exam efficient (see note)	Engine Room Skylights ... good	Copper, or Y.M. (State if on Felt.)
Caulking of Decks ... "	Ceiling ...	Coal Bunkers, Openings, Covers, &c. ...	When fitted, Month ... Year ...
Coamings ... "	Cement or Asphalt ...	Oil Bunkers ...	Boats ... not exam
Beams & Fastenings ... part exam good	Rudder ... good	Scuppers ... good	Masts, Yards, &c. ... good
Outside Plating ... good	Steering gear and its connections ...	Cargo Hatchways ...	Condition, how ascertained from deck (State if wedges removed.)
" " in way of sidelights ...	Windlass ...	Hatches ...	Equipment letter g.t. (red) 25/16 (red)
Frames ...	Have pumps been examined and found efficient? ...	Planking ...	Anchors, No. of 3B + 1S
Reverse Frames ...	Have Sluice Valves been examined and found efficient? ...	Caulking ...	Cables (State if now ranged) ...
Longitudinals part exam good	Have Watertight Doors been examined and found efficient? ...	Treenails ...	" length ... mean diam. ...
Transverses ...	Have Ventilators and their Coamings been examined and found efficient? ...	Breasthooks & Stemson ...	" Rule length ... size ...
Floors ...	Air and Sounding Pipes ... good	Transoms, Pointers & Crutches ...	Chain Locker ...
Keelsons ...	Doubling Plates under Sounding Pipes ...	Timbers of Frame at openings ...	Hawsers & Warps ... stated good
Stringers ...		" " at other places ...	Standing and Running Rigging ...
Inner Bottom Plating ...		Stringers, Clamps & Shelves ...	Sails ...
Have the Tanks been examined internally? ...		Saltine ...	
Have the Tanks been tested? ...		State if examined	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."


This ship, so far as now surveyed is, in my opinion, eligible to remain as classed with fresh record of docking 7.55, subject to corrected records of crack arrestors in flat of bottom (p.s.s.) being specially examined at the next dry docking, also to leaky transverse bulkheads in No. 7 wing tank (port side) to be dealt with at the next dry docking - homogeneous cargo to be carried in Nos 6, 7 & 8 cargo wing tanks in the meantime.

Survey Fee (per Section 23)	14.050 =	Fees applied for,
WEAR & TEAR RATE: 1/2 8.000 ton n/1	6.800 =	
Special Damage - Repair Fee (if any) ...	20.400 =	18/8/ 19.55
(per Section 23) CAR RING ...	382 =	Received by me,
Travelling Expenses (if chargeable) ...	11.605 =	19.
PART HOLIDAY FEE ...	3.500 =	
Second Surveyor's Fee (if any) REV. TAX ...	1613 =	

Committee's Minute.

THURSDAY 15 SEP 1955

Surveyor to Lloyd's Register of Shipping



011433-011440-0298 1/2

Is Certificate required? If so, to be sent to

It is recommended that this item be specially examined at the next dry docking.

WEAR & TEAR REPAIRS

Now done :- a few fractured welds in rudder plating now red out and rewelded ;
plating of rudder (S.S.) in way of upper pintle recess, found fractured,
now red out, welded and a suitable welded doubler fitted in
way.

- cargo tank No 8 (centre): bottom longitudinal No 4 from t. (p.s.), found fractured in way of transverse bulkhead web bracket, now need out, welded and a suitable welded shoulder fitted to flange in way.

2) DAMAGE.

A) Damage stated sustained through heavy weather encountered in November 1953 whilst on voyage New York - Caripito - Bahia
in ballast.

The following repairs now carried in connection therewith:

- leakages in transverse bulkheads at fore and after end of wing tank No. 7 (S.S.) in way of longitudinal end through brackets now satisfactorily repaired by fitting welded collar plates. On completion of repairs, wing Tank No. 7 (S.S.) tested with satisfactory result.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.																	
Number of Certificates.	Anchors.*	WEIGHT EX. STOCK.			WEIGHT OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintended.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collector's Weight																
	Stream																
	Kedre																

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower

[illegible]

Tank No 7 (p.s.) in way of longitudinal end through brackets now repaired by fitting welded collar plates. As similar repairs to after end bulkhead of No.7 (p.s.) wing tank could not be carried out at this time, no hydrostatic test of this tank was carried out at this time.

B) Damage stated to have been sustained through heavy weather encountered in January 1955 on voyage from Cardon to Monmouth. The following repairs now carried out in

PLEASE, SEE CONTINUATION SHEET

connection therewith:

- Shell plating, portside: one small horizontal fracture in plate No 6 in ^{of No 3 wing tank} ~~stroke~~ below sheerstroke in way of forward side transverse ^{now} ~~stroke~~ need out, welded and a suitable welded doubler fitted on inside.

Internals in way of No 3 wing tank (p.s.): web plate of forward side transverse found fractured in way of longitudinal No 6, now part renewed.

- Shell plating, starboard side: one small horizontal fracture in 4th strake below sheerstrake in way of after side transverse of No. 7 wing tank now red out, welded and a suitable welded doubler fitted on inside.

Internals in way of No 7 wing tank (S.S.) : web plate of forward and after side transverses, found fractured in way of longitudinals No 5 12 & 12, now red out, welded and suitable welded doublers fitted in way.

On completion of the above repairs shell plating is way satisfactorily tested.

Conditions of class. "Leaky transverse bulkheads in No. 7 wing tank (p.d.s.) to be dealt with next dry dkg - homogeneous cargo to be carried in Nos 6, 7 and 8 cargo wing tanks (p.d.s.) meantime".

Fore and after end bulkheads of No 7 wing tank (s.s.) now repaired and tested with satisfactory result; fore end of bulkhead of No 7 wing tank (p.s.) now repaired as stated in para. 2A above but no test carried out on completion of repairs. No repairs effected to after end bulkhead of No 7 wing tank (p.s.) owing to the difficulty of obtaining gas free certificate for hot work in No 8 wing tank (p.s.)

In view of the above it is recommended that the existing condition of class be amended to: "leakly transverse bulk-heads in No 7 wing tank (portside) to be dealt with next dry docking - homogeneous cargo to be carried in Nos 6, 7 and 8 cargo wing tanks (portside) meantime".

Interim Certificate issued - copy attached.