

Rpt. 8.

(Received at London Office

22 SEP 1950

No. 56,916

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report... 18th. Sept. 50. When handed in at Local Office... 21. Sept. 1950. Port of... CARDIFF  
No. in Reg. Book... 60615 on the ~~Woodhouse~~ Steel Sc. "GATINEAU PARK".  
Survey held at... BARRY. Date, First Survey... June 26th. Last Survey... Sept. 2nd. 1950.  
(No. of Visits... 22.)

Yes

Now.

TONNAGE :-  
GROSS 7128  
UNDER DK. 6704  
NET 4255  
Built at... Lauzon P.Q. By whom... Davie S.B. & Repairing Co. When... 1942 MONTH... 7.  
Owners... Cape Breton Freighters, Ltd. Owners' Address...  
(If not already recorded in Appendix to Register Book).  
Managers... S.G. Embiricos, Ltd. Port belonging to... London.

Surveyed Afloat or in Dry Dock? Afloat Name of Dock... Barry Dock. Destined Voyage...

Cell DBor DBa... feet; uE & B... feet; f... feet  
total capacity... tons. FPT... tons; APT... tons; MT... feet... tons.  
Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 5605. Port... ~~Cardiff~~ ~~Port~~ ~~Cardiff~~

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } - ft. - ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR (a) Conversion for the carriage of Oil Fuel.  
(b) Part Special Survey.

Now done - Vessel afloat.

Nos. 2, 3, & 4 D.B. tanks and crossbunker have been converted to carry oil fuel in accordance with plan approved. on 30.6.50.

The seams of tank top plating and cross bunker bulkheads have been reinforced with welding.  
The forward bulkheads of crossbunker have been fitted with wood lining and gutterways fitted in hold and stokehold in way of both bulkheads draining to bilge pockets which are fitted with suction.

The settling tanks are incorporated in deep tanks (crossbunker).

The D.B. tanks, deep tanks (crossbunker) and settling tanks have been tested to Rule requirements PTO.

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Decks Satisfactory	Satisfactory	Satisfactory	(State if on Felt.)
Caulking of Decks "	"	"	When fitted, Month Year
Coamings "	"	Satisfactory	Boats Satisfactory
Beams & Fastenings "	"	"	Masts, Yards, &c. "
Outside Plating "	"	"	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights. "	"	"	Equipment letter a+
Frames Satisfactory	"	"	Anchors, No. of 3B. 1S.
Reverse Frames "	"	"	Cables (State if now ranged) not ranged
Longitudinals "	"	"	" length - mean diamr. - (on board.)
Transverses "	"	"	" Rule length - size -
Floors Satisfactory	"	"	Chain Locker -
Keelsons "	"	"	Hawsers & Warps sufficient
Stringers "	"	"	Standing Rigging satisfact.
Inner Bottom Plating "	"	"	Sails -
Have the Tanks been examined internally? Yes	"	"	
Have the Tanks been tested? all but No. 7.	"	"	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is eligible in my opinion to remain as classed in the Register Book without fresh record of survey, with notation "Fitted for oil fuel 9,50 F.P. above 150°F." and to have notation "S.S. Cardiff 9,50" on completion of Special Survey, subject to supply of 45 fathoms cable.

Survey Fee (per Section 29) S.S. 49 : . : . Fees applied for,  
Oil Fuel Conversion 49 7 : . : .  
Special Damage or Repair Fee (if any) : : :  
(per Sec. 29)  
Travelling Expenses (if chargeable) 2 16 : : :  
Late Fees. 12 12 : : :  
Second Surveyor's Fee (if any) : : :  
Received by me, 21 Sept 1950  
12.10.1950

Committee's Minute

Character Assigned

Lph. 3.11.50

As now, subject (with endorsement)  
Fitted for oil fuel 9,50 FP above 150°F.  
85 9,50

011646-011656-0005

Has a Survey also been held on the Machinery of the Ship?  
If so, is the Report sent or when will it be sent?

MADE AND PRINTED IN ENGLAND.  
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Is Certificate required? If so, to be sent to



9.

If this sheet is copied by Conving Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

A watertight door now fitted on Engine room bulkhead to tunnel recess has control rods fitted to upper deck level. The door has been tested and found tight.

Holds, tween decks, superstructures, peaks, bunkers, engine and boiler spaces examined and steelwork found scaled and coated. Close and spar ceiling and pipe casings removed as required for examination of structure in way Air & sounding pipes examined. Nos. 1, 2, 3, 4, 5, 6 & 8 double bottom tanks, fore and after peak tanks and deep tanks examined internally and tested to Rule requirements, No.7 double bottom tank examined internally but time did not permit testing.

Decks, casings, coamings, boats, masts and rigging (report herewith) and general equipment examined. Pump and watertight door tested. Plating in way of sidelights examined.

To complete Special Survey: the following items require to be examined. ✓

Bottom and side shell and rudder. Anchors and cables to range. Chain locker, windlass and steering gear to examine. No.7 D.B.tank to test.

Freeboard marks to verify Hatch covers, supports, ventilators, all closing appliances.

Renewal freeboard survey to carry out.

Owners Representative advises intention of completing Special Survey

Subject item of Cardiff Report No.56805 - 45 fathoms of cable not yet supplied.

The cargo battens are complete in all holds and tween decks.

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT 'OF STOCK.			TEST PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight																
	Stream.....																
	Kedge .....																

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

his Certificate in  
While the Com  
ed, it is to be un  
er to be held re  
n the Register  
mittees or any

10.) 40m, 9, 49.